

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO. NM-014378
2. NAME OF OPERATOR Texaco Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box EE, Cortez, Co. 81321	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1850' FNL and 2310' FEL	8. FARM OR LEASE NAME H. J. Loe "B" Federal
14. PERMIT NO.	9. WELL NO. #2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5668' DF	10. FIELD AND POOL, OR WILDCAT PC
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 23 T29N R12W
	12. COUNTY OR PARISH San Juan
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Texaco Inc. proposes to plug and abandon the H. J. Loe "B" Federal #2 as follows:

Procedure:

1. Fill Hole w/9.2 ppg mud.
2. Spot 100' cement plug from 2368'-2268' inside 5½ csg to cover Top of Chacra.
3. Spot 100' cement plug from 1752'-1652' inside 5½ csg to cover Top of Pictured Cliffs.
4. Spot 100' cement plug from 1490'-1390' inside 5½ csg to cover Top of Fruitland.
5. Shoot 4-way squeeze holes @ 562'. Establish rate. Pump 150 sxs cement. Displace w/5½ bbls to 225'. Plug will cover base of Ojo Alamo, Top of Ojo Alamo and surface casing shoe.
6. Set 50' surface plug.
7. Install P & A marker. Rehabilitate location.

Necessary paperwork has been submitted to the District office for final approval.

18. I hereby certify that the foregoing is true and correct

SIGNED

Alan A. Kleier

TITLE Area Superintendent

DATE 8/6/87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

BLM (4) NMOCC (2) LAA JNH AAK

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCC

RECEIVED

AUG 12 1987

OIL CON. DIV

