

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. SF-078931-B
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 3249, Englewood, CO 80155		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FNL, 990' FWL Unit D		8. FARM OR LEASE NAME Callow A
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether SP, WT, GR, etc.) 5300' GL		10. FIELD AND POOL, OR WILDCAT Basin Dakota
		11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA Sec. 27, T29N, R13W
		12. COUNTY OR PARISH 13. STATE San Juan NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Tenneco requests permission to mill out a Model D pkr to expose an isolated Dakota "B" zone according to the attached detailed procedure.

RECEIVED  
MAY 22 1985  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Sr. Regulatory Analyst DATE May 13, 1985

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

0065/3

LEASE Callow AWELL NO. 1CASING:

9 5/8 "OD, 40 LB, N-80 CSG.W/ 175 SX

TOC @ surf . HOLE SIZE 13 3/4" DATE \_\_\_\_\_

REMARKS \_\_\_\_\_

4 1/2 "OD, 9.5 LB, J-55 CSG.W/ 300 SX

TOC @ \* . HOLE SIZE J-55 DATE \_\_\_\_\_REMARKS \*Temp Survey on 1st stage-TOC=4650'

\_\_\_\_ "OD, \_\_\_\_\_ LB, \_\_\_\_\_ CSG.W/ \_\_\_\_\_ SX

TOC @ \_\_\_\_ . HOLE SIZE \_\_\_\_ DATE \_\_\_\_\_

REMARKS \_\_\_\_\_

TUBING:

2 3/8 "OD, 4.6 LB, J-55 GRADE, 8 RD, \_\_\_\_\_ CPLG

LANDED @ ± 5770 . SN, PACKER, ETC. MODEL D @ 5773'

\_\_\_\_ "OD, \_\_\_\_\_ LB, \_\_\_\_\_ GRADE, \_\_\_\_\_ RD, \_\_\_\_\_ CPLG

LANDED @ \_\_\_\_ . SN, PACKER, ETC. \_\_\_\_\_

PUMP \_\_\_\_\_ RODS \_\_\_\_\_ ANCHOR \_\_\_\_\_

DETAILED PROCEDURE:

1. MIRUSU. Kill well w/1% KCL water. NDWH. NUBOP.
2. Tag PBTD. Tally out of hole w/ 2-3/8" tbg.
3. RIH w/Baker Model "CC" milling tool on 2-3/8" tbg w/ junk basket above tool..
4. Mill up remainder of Model "D" and push to PBTD. Use N<sub>2</sub> foam for milling. POOH.
5. RIH w/tbg w/ S.N. one joint off bottom. Land @ 5790', ~~5773'~~. NDBOP. NUWH.
6. Kick well around w/N<sub>2</sub> if necessary.
7. R.T.P.

174

DV @ 1331'

5670  
5692  
5775  
5810

MODEL D  
@ 5773'

PBTD 5849

5883