Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR ...

FORM APPROVED

BUREAU OF	LAND MANAGEMENT	Budget Bureau No. 1004-0135		
	200 MAR 20 FM 2: 03	Expires: March 31, 1993		
	S AND REPORTS ON WELLS	5. Lease Designation and Serial No. NM-014378		
	drill or to deepen of reently to a different reservoir.	6. If Indian, Alottee or Tribe Name		
Use "APPLICATION F	FOR PERMIT —" for such proposal 56/8			
SUBM	IT IN TRIPLICATE	7. If Unit or CA, Agreement Designation		
1. Type of Well: OIL GAS WELL	OTHER REPUBLICATE	8 Vell Name and Number		
WELL WILL		LOE FEDERAL B		
Name of Operator FOUR STAR OIL A	ND GAS COMPANY	[55] 34		
3. Address and Telephone No. 3300 N. Butler Ave.	Ste 100 Farmington NM 87401 325-4397	9. API Well No. 3004507955		
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)	10. Field and Pool, Exploratory Area		
Unit Letter M : 890 Feet From Th	ne SOUTH Line and 790 Feet From The	BASIN DAKOTA (PRORATED GAS)		
		11. County or Parish, State		
WEST Line Section 23	Township 29N Range 12W	MA, NAUL NAS		
12. Check Appropriate	Box(s) To Indicate Nature of Notice, Re	port, or Other Data		
TYPE OF SUBMISSION		PE OF ACTION		
	Abandonment	Change of Plans		
	✓ Recompletion	New Construction		
	Plugging Back	Non-Routine Fracturing		
Subsequent Report	Casing Repair	U Water Shut-Off		
Final Abandonment Notice	Atlering Casing	Conversion to Injection		
	OTHER: plug PC & produce D			
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true verticle depths for all markers and zones pertinent to this work.)*.				
Four Star Oil and Gas Co. has completed the follo	owing in the subject well			
3/4/2000 Move in, rig up. Nipple down well head and nipple up BOP. Tag fill at 1955'. Trip out of hole with 62 joints 2-3/8" EUE J-55 tubing(1955').				
3/6/2000 Trip in hole with 4-1/2" packer and 2-3/8" tubing to 1885. Test bridge plug to 2000#. Trip out of hole with packer and pick up 4-1/2"				
cement retainer, trijp in hole with retainer and set at 1441'. Rig up Halliburton and pump cement into PC formation as follows, pumping cement at 2.5 bbls per minute; lead slurry@ 15.6#/gal of 75 sacks class B cement with .4% HALAD-344,2% CC Tail slurry @ 15.6#/gal of 50 sacks Class				
B cement with .4% HALAD-344, 3# GILSONITE, 2% CC. Dispace tubing, sting out of retainer, pull up hole and reverse out.				
3/7/2000 Trip in hole with 3-7/8" drill bit, bit sub, 6 joints 3-1/8" drill collars and 2-3/8" tubing. Tag cement at 1426' Pick up power swivel, break circulation with water and drill cement to 1576'. Test casing to 500#. Pull up in casing.				
3/8/2000 Drill out cement to 1625, test casing to 500#. Tag fill at 1955 and clean out to 2010. Trip out of hole with tubing and collars.				
Trip in hole with retreiving tool(4-1/2") and trip out with bridge plug. Trip in hole with 3-7/6" bit and tubing, tag fish at 5518' 3/9/2000 Trip out of hole with bit and tip in with 3-3/4" wash over shoe, 9 joints wash pipe, (3-3/4")XO, jars and 6 joints 3-1/2" collars, and 160				
joints 2-3/8" tubing to fish at 5518". Wash over fish to 5781". Trip out of hole.				
3/10/2000 Run in hole with 3-3/4" overshot, 2-19/32" grapple, bumper sub, jars, drill collars and tubing to 5518' Latch on to fish and and jar for 2 hours. Over shot now stuck. Rig up wire line and do chemical cut at 5535' Rig down wire line and trip out of hole with cut off piece of tubing.				
2 hours. Over shot now stuck. Rig up wire line ar Run 4-1/2" casing scraper. Rig down. Will evalua		it of hole with cut off piece of tubing.		
Truit - 1/2 odding bordpor. Trig down. Trin Grand	is for flow steps.			
14. I hereby certify that the foregoing is true and correct	· Fac Assistant			
SIGNATURE Cuthun D. Cuch	TITLE Eng. Assistant	DATE 03/16/2000		

14. I hereby certify that the foregoing is true and correct SIGNATURE	. Cuching TITLE Eng. Assistant	DATE 03/16/2000
TYPE OR PRINT NAME	Arthur D. Archibeque	ACCESSED FOR RECORD
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE.
CONDITIONS OF APPROVAL, IF ANY:	NWOCD	<u> </u>
Title 18 U.S.C. Section 1001, makes it a crime		gency of the United States any false fictitious or foundations statements