

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ P & A		5. LEASE DESIGNATION AND SERIAL NO. 14-20-0603-9594										
2. NAME OF OPERATOR Claude C. Kennedy		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribal										
3. ADDRESS OF OPERATOR 1249 Chaco Ave., Farmington, New Mex. 87401		7. UNIT AGREEMENT NAME										
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2475'fsl, 1125'fsl		8. FARM OR LEASE NAME Clindy Lou										
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5155 Gr	9. WELL NO.										
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		10. FIELD AND POOL, OR WILDCAT Wildcat										
NOTICE OF INTENTION TO: <table border="0"> <tr> <td>TEST WATER SHUT-OFF ☐</td> <td>PULL OR ALTER CASING ☐</td> </tr> <tr> <td>FRACTURE TREAT ☐</td> <td>MULTIPLE COMPLETE ☐</td> </tr> <tr> <td>SHOOT OR ACIDIZE ☐</td> <td>ABANDON* ☐</td> </tr> <tr> <td>REPAIR WELL ☐</td> <td>CHANGE PLANS ☐</td> </tr> <tr> <td>(Other) ☐</td> <td></td> </tr> </table>		TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	SHOOT OR ACIDIZE ☐	ABANDON* ☐	REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐		11. SEC. T. R. M., OR BLK. AND SURVEY OR AREA 11, 29N, 17W
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐											
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐											
SHOOT OR ACIDIZE ☐	ABANDON* ☐											
REPAIR WELL ☐	CHANGE PLANS ☐											
(Other) ☐												
		12. COUNTY OR PARISH 13. STATE San Juan New Mex.										

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug and abandon as per verbal instructions USGS, John Ward, 5-1-1968.
Bottom plug 900 to 1100, 14 sacks,
Top plug 100 to 300, 12 sacks,
Surface plug with 5 sacks,
Erect 4 x 4 standard dry hole marker,
Job complete 5-2-1968 @ 2:00 PM.



RECEIVED

MAY 9 1968

U. S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by **CLAUDE C. KENNEDY** TITLE Operator DATE 5-6-1968

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-366229

897-851

