

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
FEB 21 1995

Sundry Notices and Reports on Wells

OIL CON. DIV.
DIST. 3

1. Type of Well

GAS

2. Name of Operator

MERIDIAN OIL

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1530'FNL, 1100'FEL, Sec.9, T-29-N, R-11-W, NMPM

5. Lease Number

NM-03486A

6. If Indian, All. or

Tribe Name

7. Unit Agreement Name

8. Well Name & Number

Lloyd A #3

9. API Well No.

30-045-21677

10. Field and Pool

Aztec Pictured Cliffs/
Otero Chacra

11. County and State

San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other -	

13. Describe Proposed or Completed Operations

2-7-95 MIRU. ND WH. NU BOP on Pictured Cliffs tbq. Circ well clean w/10 bbl wtr. Plug #1 pump 50 sx Class "B" cmt inside Pictured Cliffs 2 7/8" tbq @ 300-2100'. TOC @ 300'. POOH. ND BOP from Pictured Cliffs tbq. WOC. NU BOP on Chacra tbq. TIH to 1624'. Circ well clean w/15 bbl wtr. POOH to 1561'. SI. SDON.

2-8-95 TIH to 1880'. Circ 2 7/8" tbq clean w/8 bbl wtr. TIH to 2300', unable to go deeper. POOH to 2286', circ hole clean w/10 bbl wtr. (Verbal approval to chg plans from Steve Mason of BLM). Plug #2: pump 58 sx Class "B" cmt inside Chacra tbq @ 230-2286'. POOH to 223', circ well clean. POOH. WOC. TIH on Chacra side. Tag cmt @ 230'. PT 2 7/8" tbq to 500 psi, OK. POOH. ND BOP on Chacra side. TIH on Pictured Cliffs side, tag cmt @ 246'. POOH. TIH on Chacra side. Perf 2 sqz holes @ 187'. POOH. Establish circ out bradenhead w/6 bbl wtr. Plug #3: pump 93 sx Class "B" cmt down 2 7/8" Chacra tbq from 187' to surface. Circ 1 bbl good cmt out bradenhead. SI Chacra side. Open Pictured Cliffs tbq. Pump 5 sx Class "B" cmt down 2 7/8" tbq from surface to 180'. Circ 1/2 bbl cmt out. SI. WOC. SDON.

2-9-95 ND BOP. Cut off WH. Found cmt down 5' in Pictured Cliffs 2 7/8" tbq, at surface in Chacra 2 7/8" tbq, & down 10' in 9 5/8" csg annulus. Filled Pictured Cliffs tbq & annulus w/5 sx Class "B" cmt. Install dry hole marker w/10 sx cmt. RD. Well plugged and abandoned 2-9-95.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 2/15/95

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any:

Date **APPROVED**

FEB 17 1995

DISTRICT MANAGER

NMOCD