



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenberg
Director

Oil Conservation Division

October 17, 2002

Yolanda Perez
San Juan Regulatory
ConocoPhillips
PO Box 2197 WL 3046
Houston TX 77252

RE: Hamner 3A, E-29-29N-09W, API 30-045-23478

Dear Yolanda:

The 2002 Packer Leakage Test on the referenced well indicates there is a hole in the tubing.

Review Rule 112-A.2.b

...."Test results shall be filed with the Division within 20 days of test completion. In the event a segregation and/or packer leakage test indicates communication between separate pools, the operator shall immediately notify the Division and commence corrective action on the well."

In order to comply with Rule #112A, you are hereby directed to initiate remedial activity and retest the well to show separation of the zones prior to December 15, 2002.

Reference: CTP0228954041 on all future correspondence.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

xc: CTP File
Well File