
eras or la

5. LEASE

UNITED STATES

BW ... 3.~

DEPARTMENT OF THE INTERIOR	SF 0/8//3	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT N Rosa Unit	IAME
not use this form for proposals to drill or to deepen or plug back to a different rvoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NA Rosa Unit	ME
1. oil gas well X other 2. NAME OF OPERATOR	9. WELL NO. #77	
Northwest Pipeline Corporation 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT Blanco MV & Basi	NAME In Dakota
P.O. Box 90, Farmington, N.M. 87401	11. SEC., T., R., M., OR AREA	BLK. AND SURVEY OR
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	Sec 33 T31N	R5W
AT SURFACE: 1820' FSL & 810' FWL AT TOP PROD. INTERVAL: Same as above	12. COUNTY OR PARISH Rio Arriba	New Mexico
AT TOTAL DEPTH: Same as above 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHO) 6351' GR	w DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE SHOOT OR ACIDIZE SHOOT OR ACIDIZE SHOOT SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF:		
REPAIR WELL	(NOTE: Report results of polynomials on Form \$	nuitiple completion or zone
MULTIPLE COMPLETE		
CHANGE ZONES	•	3/4/
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine 12-31-80 MOL & RU. PU 4-3/4" bit on 2-3/8" the tested csg to 6000 psi for 30 min - OK. GO ran GR/CC1 Logs. Made 1 gun run. Per w/ a total of 10 holes.	nt to this work.)* og. Cleaned out to Circ hole w/ 2% K	o 8146'. Pressure Cl. TOH w/ tbg.
1-1-81 Perfed 24 holes from 8074' to 8085' @ 2 @ 2 SPF: 36 holes from 8035' to 8053' @ wtr & dropped 120 balls (25.5 BPM @ 3800# off. ISIP 2960#. Ran junk basket and rebridge plug at 8030'. Tested csg & plug 7989' to 8008' w/ 2 SPF. Broke down perfect 4230#). Balled off. ISIP 3140#. Go many transfer of the standard off.	2 SPF. Broke dow †). Good ball act ecovered 107 balls to 6000# OK. Go fs and dropped 60 ran junk basket &	m peris W/ RCL tion but no ball s. Set retrievable perfed 40 holes from balls (25.6 BPM recovered 11 balls.
Subsurface Safety Valve: Manu. and Type	S	et @ Ft.
18. Thereby certify that the foregoing is true and correct	lork Jan 6	1981
SIGNED Dorma Brace TITLE Production C.		7, 1301
(This space for Federal or State of APPROVED BY		
CONDITIONS OF APPROVAL, IF ANY:	UNIC	
NMOCG		

*See Instructions on Reverse Side