					1	Hudaat D	HERON NA	1004 010
orm 3160-5 jovember 1983)		UNITED STATE		BUBMIT IN TRIPI	00	Expires A	Bureau No. August 31,	1985
'ormerly 9-331)		MENT OF THE I	MIERIOR	erse side)		5. LEASE DESIGN		SERIAL NO.
	BUREA	U OF LAND MANA	GEMENT	· · · · · · · · · · · · · · · · · · ·		SF-07876		
NUS	IDRY NOT	ICES AND REPO	ORTS ON \	WELLS		6. IF INDIAN, AT	LLOTTEE OR	TRIBE NAM
(Do not use this	form for propos	als to drill or to deeper ATION FOR PERMIT—"	or plug back to	a miletent teactant				
	USE AFFLICA	TION FOR FERMIT	for such proposi	KECFIVE	J -	7		
OIL GAS	X OTHER					7. UNIT AGREEM	ENT NAME	
WELL WELL WELL	LAJ OTHER			9UG 2 5 1986				
	nolina Can	nonation	•	100 2 1300	'	8. FARM OR LEA		
Northwest Pi		poration	RIBEAL	FLAND MANAG	VEX. 15.	Rosa Uni	1t 	
	· -	NM 07400	FADALIA	NGTON RESOURCE	EMENT	9. WELL NO.		
P.O. Box 90	- rarmingt	on, NM 87499 learly and in accordance				#102		·
See also space 17 bel	10W.)	SL & 900 FEL		equitements.*		Laguna S	seca Ga	LDCAT
•	1790 F	SL & 900 FEL	NE/4 3E/4		-	<u>Basin</u> Da	akota	•
					[11. SHC., T., E., I SURVEY O	M., OR BLK. A B ARMA	IND
PERMIT NO.		15. ELEVATIONS (Show	whether DF BT CB	etc.)		Sec. 30	, T31N,	R5W_
		i	whether br, ki, Gk,	euc.)			1	
-		6428' GR				Rio Arr	1ba No	ew Mex
	Check Ap	propriate Box To In	dicate Nature	of Notice, Repo	rt, or Oth	ner Data		
	NOTICE OF INTENT		1	, ,		T REPORT OF:		
		۲				··· uarour of .		
TEST WATER SHUT-O		PULL OR ALTER CASING	-	WATER SHUT-OFF		REPAI	IRING WELL	
FRACTURE TREAT		CULTIPLE COMPLETE		FRACTURE TREATME	NT	ALTE	BING CASING	
SHOOT OR ACIDIZE	^	BANDON*		SHOOTING OR ACIDIZ		ABANI	DONMENT*]
REPAIR WELL	[c	HANGE PLANS		(Other) Remed				
(Other)		RATIONS (Clearly state al nally drilled, give subsu		Completion or	Recompleti	multiple comp on Report and	detion on W Log form.)	ell
7-25-86 MOL. RU rig	. Killed	tbg. ND wellh	ead. Shut		ekend.			
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T"	et and TOH. egone). T 4-1/2" R-3 sleeve, an	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac	jts of the collar. 1 h temperate -3/8" tbg.	down for we g (top seal jt 2-3/8", ure rubbers,	on pac seatin	g nipple, 2-3/8", ne	18 jts ew Bake	r
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T"	t and TOH. gone). T 4-1/2" R-3 sleeve, an 03'. Set	Total of 248 IH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac	jts of the collar. 1 h temperate -3/8" tbg.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating l jt:	g nipple, 2-3/8", no . Set tbo	18 jts ew Bake g at 80	r
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29	at and TOH. gone). T 4-1/2" R-3 sleeve, an O3'. Set Rig down	Total of 248 IH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac	jts of the collar. 1 h temperate -3/8" tbg.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating l jt:	g nipple, 2-3/8", no . Set tbo	18 jts ew Bake g at 80	r
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig	at and TOH. gone). T 4-1/2" R-3 sleeve, an O3'. Set Rig down	Total of 248 IH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac	jts of the collar. 1 h temperate -3/8" tbg.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt 246 jts	g nipple, 2-3/8", no . Set tbo	18 jts ew Bake g at 80	r
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead.	t and TOH. gone). T 4-1/2" R-3 sleeve, an 03'. Set Rig down	Total of 248 IH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac	jts of the collar. I h temperate -3/8" tbg. ker.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt 246 jts	g nipple, 2-3/8", no . Set tbo	18 jts ew Bake g at 80	r
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7	t and TOH. gone). T 4-1/2" R-3 sleeve, an O3'. Set Rig down	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac	ejts of the collar. I h temperate -3/8" tbg. ker.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating l jt 246 jts AUG 2 DIST	g nipple, 2-3/8", ne Set tby 8/986 V. DIV. aker retr	18 jts ew Bake g at 80	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ l jt,	t and TOH. gone). T 4-1/2" R-3 sleeve, an 03'. Set Rig down Release	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack	ejts of the collar. I h temperate -3/8" tbg. ker.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating l jt 246 jts AUG 2 DIST	g nipple, 2-3/8", no 2-3/8", no 3	18 jts ew Bake g at 80	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ 1 jt,	t and TOH. gone). T 4-1/2" R-3 sleeve, an 03'. Set Rig down Release	Total of 248 IH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack sipple with pum	e jts of the collar. I h temperate -3/8" tbg. ker.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt : 246 jts AUG 2 L COI DIST	g nipple, 2-3/8", no 2-3/8", no 3 1986 N. DIV. 3 aker retred on back	18 jts ew Bake g at 80 ieve-a-k	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ 1 jt, I hereby certify that SIGNED Carrie	Release seating n the foregoing is Harmon	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack sipple with pum true and correct	e jts of the collar. I h temperate -3/8" tbg. ker.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt : 246 jts AUG 2 DIST	g nipple, 2-3/8", no 2-3/8", no 3 1986 V. DIV. 3 aker retred on back	18 jts ew Bake g at 80 ieve-a-k 8-22-	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ l jt,	Release seating n the foregoing is Harmon	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack sipple with pum true and correct	e jts of the collar. I h temperate -3/8" tbg. ker.	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt : 246 jts AUG 2 DIST	g nipple, 2-3/8", no 2-3/8", no 3 1986 V. DIV. 3 aker retred on back	18 jts ew Bake g at 80 ieve-a-k 8-22-	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ l jt, I hereby certify that signed Carrie (This space for Feder	Release seating n the foregoing is Harmon	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack sipple with pum true and correct domon true	jts of the collar. 1 h temperate -3/8" tbg. ker. er & TOH. p out plug	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt : 246 jts AUG 2 DIST	8 1986 V. DIV. aker retred on back	18 jts ew Bake g at 80 ieve-a-k 8-22-	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ l jt, I hereby certify that SIGNED Carrie (This space for Feder	Release seating n the foregoing is Harmon ral or State office	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack dipple with pum true and correct MMOL TITE E use)	jts of the collar. 1 h temperate -3/8" tbg. ker. er & TOH. p out plug	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt : 246 jts AUG 2 DIST	g nipple, 2-3/8", no 2-3/8", no 3 1986 V. DIV. 3 aker retred on back	18 jts ew Bake g at 80 ieve-a-k 8-22-	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ l jt, I hereby certify that signed Carrie	Release seating n the foregoing is Harmon ral or State office	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack dipple with pum true and correct MMOL TITE E use)	jts of the collar. 1 h temperate -3/8" tbg. ker. er & TOH. p out plug	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt 246 jts AUG 2 L COI DIST	Set the Set th	18 jts ew Bake g at 80 ieve-a-k). 8-22-	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ l jt, I hereby certify that SIGNED Carrie (This space for Feder	Release seating n the foregoing is Harmon ral or State office	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack dipple with pum true and correct MMOL TITE E use)	jts of the collar. 1 h temperate -3/8" tbg. ker. er & TOH. p out plug	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating 1 jt 246 jts AUG 2 L COI DIST	8 1986 V. DIV. aker retred on back	18 jts ew Bake g at 80 ieve-a-k). 8-22-	r 30'
MOL. RU rig 7-28 Release donu rubbers were 2-3/8", new sliding "T" packer at 74 7-29 NU wellhead. 8-5 MOL & RU rig 8-6 ND wellhead. 8-7 TIH w/ l jt, I hereby certify that SIGNED Carrie (This space for Feder	Release seating n the foregoing is Harmon ral or State office	Total of 248 TH w/ notched packer w/ hig d 226 jts of 2 18,000# on pac rig. donut and pack tipple with pum true and correct TIT: e use) TIT:	jts of the collar. 1 h temperate -3/8" tbg. ker. er & TOH. p out plug	down for we g (top seal jt 2-3/8", ure rubbers, Total of 2	on pac seating l jt 246 jts AUG 2 DIST B/8", B continue	Set the Set th	18 jts ew Bake g at 80 ieve-a-k). 8-22-	r 30'