

UNITED STATES
DEPARTMENT OF INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to
deepen or plug back to a different reservoir.
Use Form 3160-3 for such proposals.)

1. Oil well Gas Well Other
Gas Well

2. Name of Operator
Parker & Parsley Development Company

3. Address & Telephone No. (505) 334-2555
c/o A. R. Kendrick, Box 516, Aztec, NM 87410

4. Location of Well (Footage & S.T.R.)
1830' FNL 850' FEL, H-2-T31N-R4W

5. Lease Designation and Serial No.
SF-078891

6. If Indian, Allottee or Tribe Name.

7. If Unit or CA, Agreement Designation.
ROSA UNIT

8. Well Name and No.
ROSA UNIT #283

9. API Well No.
30-039-24856

10. Field and Pool, or Exploration Area
Basin-Fruitland Coal Gas Pool

11. County or Parish, State
Rio Arriba, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input checked="" type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	<input type="checkbox"/> Dispose Water

RECEIVED
APR 9 1992
OIL CON. DIV.
DIST. 3

17. Describe Proposed or Completed Operations (Give Pertinent Details and Dates.)

6/4/91 Move in & rig up completion unit. Install BOP. Pressure test BOP, casing & choke manifold to 800 psi, held OK. TIH w/bit, tag cement @ 3710', clean out to 4148' KB. SDON.

6/5/91 SICP = 0 psi. Ran GR-CCL-CBL @ 800 psi 4130'-2100'. Good 95% bond 3530'-4130'.
Perforate Fruitland Coal 4062'-4082' @ 2 spf, total 42 x 1/2" diameter, 120 degree phased holes.

6/6/91 Broke down perf @ 2' intervals,

6/7/91 Install treesaver & test backside to 1000 psi, test OK. Sand Water Frac w/80,094 gal 25# linear x-link gel w/25,000# 40/70 plus 206,710# 20/40 sand.

6/8/91-6/10/91 Clean out after frac.

6/11/91 Tag PBTD @ 4148'. Landed 2-7/8" tubing @ 4041'.

RECEIVED
BLM
92 APR -1 AM 11:12
519 FARMINGTON, N.M.

NOTE: This format is issued in lieu of U.S. BLM Form 3160-5.

14. I hereby certify that the foregoing is true and correct.

Signed A.R. Kendrick Title _____ Agent _____ Date 3/31/92

Approved by _____ Title _____

Conditions of approval, if any:

MOOD BY E. J. B. DATE APR 16 1992

ACCEPTED FOR RECORD
FARMINGTON RESOURCE AREA