In Lieu of Form 316 (June 199	0 DEPARTME	ED STATES NT OF INTERIOR AND MANAGEMENT	FORM APPROVED Budge: Bureau No. 1004-0135 Exp.res: March 31, 1993	
SUNDRY NOTICE AND Do not use this form for proposals to drill or to deepen of		or reenty to a different reservoir. Use "APPLICATION	5. Lease Designation and Serial No. SF-078767	
	TO DRILL" for perm	it for such proposals	6. If Indian, Allottee or Tribe Name	
	SUBMIT IN T	RIPLICATE	75 If Unit or CA, Agreement Designation ROSA UNIT	
1.	Type of Well ☐ Oil Well ☐ Gas Well ☐	Other Third	8. Well Name and No. ROSA UNIT #125	
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	DEGETVE!	9. API Well No. 30-039-25144	
3.	Address and Telephone No. PO BOX 3102 MS 37-4, TULSA, OK 74101	(918) 588-4592 NOV 3 0 1990	10. Field and Pool, or Exploratory Area 10. 16NACIO BLANCO DK/MV	
- 4.	Location of Well (Footage, Sec., T., R., M., 6 970' FNL & 1190' FEL, NW/4 NE /4 SEC 13	or Survey Description) OIL GOING BUT -31N-6W DIST. 3	11. County or Parish, State RIO ARRIBA, NM	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION		ТҮРЕ	YPE OF ACTION	
	□ Notice of Intent	□ Abandonment	☐ Change of Plans	
	■Subsequent Report	□ Recompletion □ Plugging Back	□ New Construction□ Non-Routine Fracturing	
	☐ Final Abandonment	□ Casing Repair □ Altering Casing	☐ Water Shut-Off ☐ Conversion to Injection	
	- Fmai Abandonment	Other COMPLETION	☐ Dispose Water	
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. I well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*				
11-05-1998 Rig up rig and spot equipment. SICP = SITP = 580#. Blow well down. ND wellhead and NU BOP. TOH with 156 jts. of 2-3/8" tubing. TIH with 3-7/8" bit to 4895'. Pick up swivel and lay gas lines. SDON.				
11-06-1998				
Tag 5' of fill @ 4970'. Clean out to CIBP @ 4975' w/ drill gas. Drill out CIBP & chase to 6252'. Blow well w/ drill gas, bucket test: 5,7 bwph & 1/2 cup of sand. Pull up to 5880' & turn over to night watch. Will alternate blowing & flowing well.				
11-07-1998				
TIH and blow well. Flow well naturally and pitot test at 2,148 MCFD (dry). TOH and found split collar on joint #163. TIH with production tubing. Blow well. Returns are light water with a trace of sand. Land 192 jts (6022.95') of 2-3/8", 4.7#, J-55, EUE tubing at 6038' KB. SN is on top of bottom joint at				
6007' KB. ND BOP and NU wellhead. Pump off check and kick well off with drill gas down the casing and up the tubing. Recovered load. Rig down				
and prepared to move. FINAL REPORT.				
			•	
14.	I hereby certify that the foregoing is true and	correct		
	Signed Susan GRIGUHN	Title <u>CLERK</u> I	Date November 13, 1998	
	(This space for Federal or State office use)			
	Approved by	Title	Date	
	Conditions of approval, if any:		ACCEPTED FOR RECCHD	
Title 18	U.S.C. Section 1001, makes it a crime for any puts or representations as to any matter within its	erson knowingly and willfully to make to any department jurisdiction.	or agency of the United States any fal 998 itious or fraudulen	

NMOCD

FARMINGTON DISTRICT OFFICE

ROSA UNIT #125

