## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

This form is not to be used for reporting packer leakage tests in Southeast New Mexico



Page 1 Revised 11/16/98

		NORTHWEST	NEW MEXIC	O PACKER-	LEAKAGE TEST		
Oper	ator William	5 Product	lon Lea	se Name_	Rosa	Well No <u>7</u> 9	
Location of	Well:Unit Letter	E Sec 2	- <u>Z</u> Twp <i>31)</i>	√ Rge 6 !	V API#30-0 392	1541200	
	NAME OF RESE	TYPE OF PROD. (Oil or Gas)		METHOD OF PROD. (Flow or Art. Lift)	PROD.MEDIUM (Tbg. or Csg.)		
Upper Completion	PICTURES	Go	. 5	Flow	786		
Lower Completion	MESA V	G	8<.	Flow	TRG		
		PRE-FI	LOW SHUT-I	N PRESSU	RE DATA		
Upper Completion	Hour, date shut-in		Length of time s		SI press. Psig	Stabilized? (Yes or No)	
Lower Completion	Hour, date shut-in	5-6-02	Length of time s	Hos	SI přess. Psig	Stabilized? (Yes or No)	
Commonant	(harris data) A (h A			ST NO. 1			
		ur, date). 0940		Zone producing	(Upper or Lower): UPDIR		
TIME (hour,date)	LAPSED TIME PRESSUR SINCE* Upper Completion Lov		ower Completion	PROD. ZON TEMP.	REMARKS		
0930 E-	o sitte	336	270	65	<b>D</b>		
0930 5-11	48 He	218	272	671	2		
	72He						
1045 S-13	96HR	353	276	67	SI for 3"	& Bulo up	
			/		,		
Production ra	ate during test						
Oil:		BOPD based	on	Bbls. ir	Hours	_GravGOR	
Gas:	207	MCF	PD; Tested th	ru (Orifice(o	Meter)		
		MID-TE	ST SHUT-IN	PRESSUR	E DATA		
Upper Completion	Hour, date shut-in	Hour, date shut-in		shut-in	SI press psig	Stabilized? (Yes or No)	
Lower Completion	Hour, date shut-in 6855 5-4-02		Length of time shut-in		SI press. psig	Stabilized? (Yes or No)	

## FLOW TEST NO. 2

,nenced	l at (hour, date)*	00PO"	5-16-6	Zone producing	(Upper or Lowr): Lowers
TIME .nour,date)	LAPSED TIME Since**	PRESS Upper Completion	URE Lower Completion	PROD. ZONE	REMARKS
7920 5-17	241e	534	156	620	
1120 6-18	48 HR	551	173	65°	
1155 5-19	72HR	562	176	670	
045 S-20	96 Hæ	576	233	65°	
				<del>.</del>	

Production rate d	luring test				-
Oil:	BOPD based on MCFPD	Bbls. in	Hours	Grav	GÖR
Remarks:	•				;
I hereby certify th	at the information herein contai	ned is true and complete	to the bes of	my knowledge	t <b>.</b>
Approved	20	Operator	υŔΧ		•
	nservation Division	By B.11 =	Seevers		<del>-</del> -
Ву		Title Pos s	TECh		
PEPUTY 3	R & wat 1888 white and a con-		<u> </u>		_

## NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.

Title

- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial

packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.

- 5. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.
- Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test no. 2 is to be the same as for Flow Test No. 1 except

that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.

7. Pressures for gas-zone lests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test date.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The result s of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico oil Conservation Division on northwest new Mexico packer leakage Test Form Flevised 11-16-98 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).