

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
SF 76337	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY		8. Farm or Lease Name Helton Gas Com
3. Address of Operator 501 Airport Drive Farmington, NM 87401		9. Well No. 1
4. Location of Well UNIT LETTER 0, 790 FEET FROM THE South LINE AND 1850 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 30N RANGE 9W NMPM.		10. Field and Pool, or Wildcat Blanco Pictured Cliffs
15. Elevation (Show whether DF, RT, GR, etc.) 5702' GL		12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
P & A operations began on 6/30/78.

These operations were completed on 7/1/78 as follows:

- 1) Set cement retainer at 2276'.
- 2) Pumped 10 sx Class "B" Neat cement into perforations at 2292-2346.
- 3) Spotted 90 sx cement from 2275' to 980'. WOC.
- 4) Pumped 76 sx cement from 980' to surface.
- 5) Cut off wellhead and erected P & A marker.
- 6) Location cleaned up.

The following was left in the hole:

4-1/2" casing set at 2387' and 8-5/8" casing set at 203'.

OK 7-25-78
C.S.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By
E. E. SVOBODA

SIGNED _____ TITLE Area Adm. Supervisor DATE 7/12/78

APPROVED BY *AK Kendrick* TITLE _____ DATE JUL 20 1978

CONDITIONS OF APPROVAL, IF ANY: