NO. OF COPIES RECEIVED	Form C-103 Supersedes Old
SANTA FE I NEW MEXICO OIL CONSERVATION C	C-102 and C 102
FILE /	Friedtive 1-1-62
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	State Fee. X
OPERATOR 5	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPPEN OR PLUG BACK TO A DIFFE. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS X OTHER-	7. Unit Agreement Name
Aztec Oil & Gas Company	8. Farm or Lease Name
3. Address of Operator	McGrath 9. Well No.
P. O. Drawer 570, Farmington, New Mexico 87401	#2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER N 990 FEET FROM THE SOUTH	
THE West LINE, SECTION 34 TOWNSHIP 30N RANGE	12W NMPM.
15. Elevation (Show whether DF, RT, GR, e.	
5788' GR	(12. County San Juan
Check Appropriate Box To Indicate Nature of No	tice, Report or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	RK ALTERING CASING
TEMPORARILY ABANDON COMMENCE DR.	
PULL OR ALTER CASING CASING TEST A	ND CEMENT JOB
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give powerly SEF RULE 1003.	ertirent dates including and distributions
work) SEE RULE 1103.	starting any proposed
PROPOSE TO:	
1. Move on location and rig up.	
2. Pull 1" tubing.	
3. Spot 50 sacks cement at top of Pictured Cliffs.	
4. Perforate at base of Ojo Alamo and sque leaving 10 sacks inside pipe.	eze with 50 sacks cement
5. Perforate hole at 200' and squeeze with	50 sacks coment leaving
10 sacks inside pipe.	30 Sacks Cement Teaving
6. Spot 10 sacks cement at surface and ins	tall dry hole marker.
	A OF WALL
18. I hereby certify that the information above is true and complete to the best of my knowledge	and belief.
SIGNED TITLE DISTRICT Pro	oduction Manager May 10, 1977
02 1 2 2	
ADDROVED BY STEWER TO SEE THE STEWER TO SEE THE SEE TH	er of the second

CONDITIONS OF APPROVAL, IF ANY: