

January 28, 1970

Southern Union Production Co.

WELLS REQUIRING FILE CORRECTIONS ONLY

<u>LEASE NAME AND WELL NUMBER</u>	<u>LOCATION</u>	<u>POOL</u>	<u>PRESENT ACREAGE</u>	<u>CORRECTED ACREAGE</u>
Helms Fed. #1	K-22-30N-10W	Blanco MV	W 320.00	W 323.84
Helms Fed. #1	K-22-30N-10W	Basin Dakota	W 320.00	W 323.84
Sanchez #2	J-34-30N-10W	Aztec PC	160.00	158.54
Sanchez #3	L-34-30N-10W	Basin Dakota	S 320.00	S 316.84 ✓
Sanchez #1	M-34-30N-10W	Aztec PC	160.00	158.30



# OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO  
1000 RIO BRAZOS ROAD - AZTEC  
87410

GOVERNOR  
DAVID F. CARGO  
CHAIRMAN

LAND COMMISSIONER  
ALEX ARMIJO  
MEMBER

STATE GEOLOGIST  
A. L. PORTER, JR.  
SECRETARY - DIRECTOR

## MEMORANDUM

FROM: EMERY C. ARNOLD, SUPERVISOR, DISTRICT #3

TO:

SUBJECT: ACREAGE CORRECTIONS, TOWNSHIP 30 NORTH, RANGE 10 WEST

The Oil Conservation Commission has received a dependent resurvey of Township 30 North, Range 10 West from the General Land Office.

In conformance with Commission policy we are changing all acreage dedications of wells producing in this township to conform with new acreages shown on the new plat. We have listed these wells in two groups - first, those for which the change will not involve an allowable change because of rule tolerances in calculating allowables and second, those wells where allowables will be affected by the acreage change. In the first instance the Commission will not require that new plats be filed to effect the corrections, as you may use this list to make file corrections and the Commission will do likewise. In the second instance the Commission will require that Form C-102, Acreage Dedication Plat, be filed with this office showing the correct acreage. The dedicated acreage total should be outlined on the plat and the acreage total should be filled in the designated blank. This form should be filed in triplicate for each well. The form need not be signed by the surveyor who staked the location as properly executed location information is already on file.

It will be appreciated if you will check the acreages shown on the list to your own records and contact us if errors are found so that the final result will be as accurate as possible.

We request that the corrected acreage plats be filed as soon as possible, preferably within the next ten days.

January 28, 1970