

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

5F-043260-B

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Beta Development Co.	8. FARM OR LEASE NAME Federal "H"
3. ADDRESS OF OPERATOR 234 Petr. Club Plaza, Farmington, N. M.	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.) At surface 1190/N 1190/W	10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 33 23-30N-11W NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5985' GR	12. COUNTY OR PARISH San Juan
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☒

SHOOTING OR ACIDIZING ☒

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-21-65 Moved in rigged up completion rig. Dril DV tails @ 4929' & 2447', CO to float collar @ 6859'. PT 4000#, held OK. Spotted 500 gals 7 1/2% reg acid & calcium chloride wtr.

4-22-65 Ran junk basket twice then correlation log, bottom @ 6859'. Perf. 6847-49 & 6821-27' w/2 JPF. Acid BD 1700#. SWF w/10,000# 10-60 ad & 10,000# 20-40 ad 35,574 gals tot. wtr. TP 3900#, ATP 3600# @ 31.6 BPM. SI 2050# 5 MSI 1200#. Set cast iron BP @ 6816'. Perf. 6799-6803 & 6778-4790' w/2 JPF. After perforating 6799-6803' had communication between zones. SWF w/15,000# 20-40 ad & 21,688 gals wtr. (Sanded off w/15,000# 20-40 ad in formation flowed back to pit, pumped 64 bbl wtr, pressured to 4000#). TP 4000-3700# @ 26.8 BPM. SI 4 hrs. WTH w/bit, CO to 200' ad & dril on BP.

4-23-65 Drig BP, circ hole clean, Ran 217 jts 6832.33' 2" EUE tbg set @ 6845' w/pin collar on bottom. Kicked well off by swabbing. Rig released Saturday morning, 4-24-65.

RECEIVED

APR 27 1965

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by:

TITLE

Manager

DATE

4-26-65

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

987-851

