

F. Loc. 330/S; 1650/W Elev. 5438 GL Spd. 10-20-46 Comp. 11-20-46 TD 1630 PB
 Casing S. 12 $\frac{1}{2}$ @ 38 w10 Sx. Int. @ W Sx. Pr. 5 $\frac{1}{2}$ @ 1530 W 50 Sx. T. @
 Csg. Perf. Prod. Stim. Not Shot

T
R
A
N
S
M
I
T
T
E
D

I.P. 1500 MCF/D After 3 Hrs. SICP PSI After Days GOR Grav. 1st Del. 1-47

TOPS		NITD	Well Log	TEST DATA						Ref. No.
Kirtland		C-102	Plat X	Schd.	PC	Q	PW	PD	D	
Fruitland		C-103	Electric Log	disconnected 8-17-68						1589
Pictured Cliffs	1500	C-104 X	C-110 XXX							
Cliff House			C-122							
Menefee		Ditr	Dfa							
Point Lookout		Datr	Dac							
Mancos		Remarks NIT to test PC 9-15-87 SE/4SW/4 #380 Sec. 28 /Fkg-Redfern Oil Co. R-653 /Redfern Dev. Corp. /Redfern & Herd. 63) /M.S.B.W. 100 A-								
Gallup										
Sanostee										
Greenhorn										
Dakota										
Morrison										
Entrada										
Pcd	3918									

P
o
Ful-Kutz PC Co. SJ s 28 T 30N R 12W U N Oper Norman L. Gilbreath
 June | July | Aug. | Sept. | Oct. | Nov. | Dec. |
 Lse. Montano No. 1