Form 3160-5 -(August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
OMB NO. 1004-0135
xpires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

5.	Lease Serial No.
	NMSF078144

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

3

SUBMIT IN TRI	PLICATE - Other instructi	₹ %	MNM73715	reement, Name and/or No.		
Type of Well Oil Well		Well Name and N FOGELSON 1	.			
2. Name of Operator BURLINGTON RESOURCES	EGGY COLE -Mail: pbradfield@br-inc.com	9 API Well No. 30-045-09122	9 API Well No. 30-045-09122-00-S1			
3a. Address P O BOX 4289 FARMINGTON, NM 87499		3b. Phone No. (include area code) Ph: 505.326.9727 Fx: 505.326.9563		10. Field and Pool, or Exploratory BASIN DAK		
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)	744.2	11. County or Paris	h, and State		
Sec 26 T30N R11W SESE 10 36.77875 N Lat, 107.95454 W			SAN JUAN C	OUNTY, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	□ Water Shut-Off		
☐ Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity		
■ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	☐ Temporarily Abandon			
	☐ Convert to Injection	□ Plug Back	□ Water Disposal			
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) (6/24/02) MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg, tbg had parted due to corrosion. SDON. (6/25/02) TIH w/overshot, fish for 2-3/8" tbg. TOOH w/overshot. TIH w/mill. CO scale @ 3199-3271'. TOOH w/mill. SDON. (6/26/02) TIH w/mill to 3271'. CO to 3275'. TIH w/overshot, tag @ 3275'. TOOH w/overshot & 1 jts 2-3/8" tbg. TIH w/mill, tag fish @ 3316'. Mill out to 3321'. TOOH w/mill. SDON. (6/27/02) TIH w/overshot, attempt to engage fish. TOOH w/overshot. TIH w/mill, tag up @ 3326'. Mill @ 3326-3340'. TOOH w/mill. SDON. (6/28/02) TIH w/overshot to 3340'. Engage fish & PUH. Fish broke loose. TOOH w/overshot & 22' of fish. TIH w/mill, tag up @ 3358'. Mill out to 3366'. TOOH w/mill. SDON. (7/1/02) TIH w/mill to 3365'. Mill out to 3374'. TOOH w/mill. TIH w/overshot, could not engage fish. TOOH w/overshot. SDON. (7/2/02) (Verbal approval from Steve Mason, BLM, to plug and abandon wellbore). TIH w/cmt ret, set						
14. I hereby certify that the foregoing is true and correct. Electronic Submission #12616 verified by the BLM Well Information System For BURLINGTON RESOURCES O&G CO LP, sent to the Farmington Committed to AFMSS for processing by Seeve Mason on 07/09/2002 (02SXM0353SE)						
Name (Printed/Typed) PEGGY C	OLE	Title REPOF	RT AUTHORIZER			
Signature (Electronic	Submission)	Date 07/09/2	2002			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By ACC	EPTED		PHEN MASON ROLEUM ENGINEER Date	07/09/2002		
Conditions of approval, if any, are attached certify that the applicant holds legal or eqwhich would entitle the applicant to cond	uitable title to those rights in the		ington			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #12616 that would not fit on the form

32. Additional remarks, continued

@ 3090'. Pump 400 sxs Class III cmt. Left 120' cmt ontop of ret. Circ hole w/wtr. PT csg to 500 psi, failed. PUH to 2848'. Spot 50 sxs balanced plug from 2848' to 1700'. WOC. Tag cmt @ 1700'. Shoot 3 sqz holes @ 1160'. WOC. TIH w/ret, set @ 1040'. Cmt w/115 sxs Class III cmt. Pumped 38 sxs below ret, left 35 sxs above ret. Circ cmt 270' to surface w/30 sxs cmt. Cmt to pit. TOOH with tbg. ND BOP. Install P&A marker. RD. Rig released.

Well plugged and abandoned 7/2/02.