5 USE 1 McCulleon 1 File Form approved. Budget Bureau No. 42-R1424. Form 9-331 (May 1963) UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) 5. LEASE DESIGNATION AND SERIAL NO. 14-20-603-4904 **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTER OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) Maya jo 7. UNIT AGREEMENT NAME OIL WELL GAS WELL OTHER S. FARM OR LEASE NAME NAME OF OPERATOR McCulloch Cil Corp. of California Indian 9. WELL NO. ADDRESS OF OPERATOR Box 234, Farmington, New Mexico LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 10. FIELD AND POOL, OR WILDCAT Verde Colley 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 5ec. 1, 7508, RIGH 12. COUNTY OR PARISE 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REPAIRING WELL WATER SHUT-OFF TEST WATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Spotted 24 sx plug 1425' to T.D. Shot off caming at 2m 750'. 3. Spotted 15 ex count - 50' in casing stub and 50' out of stub. Pulled oneing Spotted 5 ax essent plug in surface. Breeted dry bole marker. DIST. 3 U. S. GEOLOGICAL SURVEY