



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Jennifer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

December 11, 2001

Kyle Beebe
Devon Energy Production Company, LP
20 N Brdwy Ste 1500
Oklahoma City OK 73102

Re: North East Blanco Unit #58, A 13-31N-07W, API 30-45-10810

Dear Mr. Beebe:

The 2001 Packer Leakage Test on the referenced well indicates communication between the producible zones.

Review Rule 112-A.2.b

...."Test results shall be filed with the Division within 20 days of test completion. In the event a segregation and/or packer leakage test indicates communication between separate pools, the operator shall immediately notify the Division and commence corrective action on the well."

In order to comply with Rule #112A, you are hereby directed to initiate remedial activity and retest the well to show separation of the zones prior to March 1, 2002. Notify the Aztec OCD in time to witness the retest

Place Compliance number: **CTP0134460125** on all communication regarding this Directive.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

Charlie T Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File