5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR	NM-27024
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N.A.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME NA 8. FARM OR LEASE NAME
1. oil gas well x other	Mesa-Twin Mounds 9. WELL NO.
2. NAME OF OPERATOR	#1
Lobo Production	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR PO Box 2364 Farmington, NM 87499	Basin Dakota
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30, T30N, R14W
AT SURFACE: 790' FNL, 990' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: same AT TOTAL DEPTH:	San Juan New Mexico
same	14. API NO.
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	15 51505
	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	(3,503 KB)
FRACTURE TREAT	
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL SHOOT OR ACIDIZE	1983
SHOOT OR ACIDIZE REPAIR WELL REPAIR OR ALTER CASING	(NOTE: Report results of multiple completion or zone
MULTIPLE COURTERS	CALLEGE OF Form 9-330.)
CHANGE ZONES	GIGAL H. M.
ABANDON*	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent.	rectionally drilled, give subsurface locations and it to this work.)*
7/8/83: Moved completion rig on location 5782 KB. Pressure test 3400#. DV tool at 3777'. Perforated in holes.	Ran CBL-Gamma Ray PBTD to
7/9/83: Acidized w/500 gal. 15% HCL. F 85,500 gal. 301b. Crosslink ge	
7/10/83 TO 7/12/83: Swabbed and flow t	
7/13/83: Flow test Kd 24 hrs. @ 572 MC	F w/801b, tubing pressure and
660 Casing pressure. Ran RBP	and set at 5400'
Pressure test to 3400#.	
Subsurface Safety Valve: Manu. and Type	Set @Ft.
18. I hereby certify that the foregoing is true and correct SIGNED TITLE QY.	DATE 8/3/83
	7 S 40 S 1, 2 S S
(This space for Federal or State off) APPROVED BY	ice tise
CONDITIONS OF APPROVAL, IF ANY:	AUG 0 3 1983
	2 2000

FARMMETER RESOURCE ANDA FARMINGTON, NEW MEX.OD

*See Instructions on Reverse Side

