

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC
NEBU# 444			
Fruitland Coal Zones:			
	3200'	3202'	
	3222'	3223'	
	3237'	3239'	
	3240'	3244'	
	3259'	3262'	
	3263'	3268'	
	3269'	3271'	
	3318'	3321'	
	3322'	3323'	
	3326'	3327'	
	3328'	3332'	
	3334'	3342'	
	3370'	3377'	

RECEIVED
JAN 4 1991
OIL CON. DIV.
DIST. 3

38. GEOLOGICAL MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH
Top PC Tongue	3391'	
Main PC	3520'	