

Submit 3 Copies to
Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM

P.O.Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-045-29647

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Atlantic D Com D LS

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
5B

2. Name of Operator
AMOCO PRODUCTION COMPANY
Attention: Mary Corley

P.O. Box 3092 Houston TX 77253

9. Pool name or Wildcat
Blanco Mesaverde

4. Well Location
Unit Letter E : 2390 Feet From The NORTH Line and 690 Feet From The WEST Line
Section 2 Township 30N Rang 10W NMPM San Juan County


10. Elevation (Show whether DF, RKB, RT, GR, etc.)
6360'

11. Check Appropriate Box to Indicate Nature of Notice Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <u>SideTrack New Completion</u> <input checked="" type="checkbox"/>	OTHER: _____ <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed)

- SIDETRACK
- MIRURT
 - Pick-up 6 1/4" tri-cone bit, bit sub, 3 pt reamer, 5" drill collars TIH (blow hole dry)
 - Drill 2539-2639(100'), wireline survey
 - TOH and pick up 6 1/4 air hammer and air hammer bit
 - TIH and drill to TD
 - Run 4 1/2 Liner
 - Cement with 50% excess and soft set packer
 - TOH lay down drillpipe
 - RDRT



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Corley TITLE Sr. Business Analyst DATE 01-20-2000
TYPE OR PRINT NAME Mary Corley TELEPHONE NO. 281-366-4491

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHARLIE T. PERREN TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JAN 27 2000

CONDITIONS OF APPROVAL, IF ANY: