5. LEASE

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	14-20-604-1850 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–0 for such proposals.)	Tte Mountain 7. UNIT ABREEMENT NAME Horseshoe Gallup Unit 8. FARM OR LEASE NAME
1. oil gas ther X - Injection	Horseshoe Gallup Unit 9. WELL NO.
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of Atlantic Richfield Company 3. ADDRESS OF OPERATOR 707-17th Street, P.O. Box 5540, Denver, CO 80217 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit "N" AT SURFACE: 660' FSL & 1980' FWL, Sec. 35 AT TOP PROD. INTERVAL: Appx. same AT TOTAL DEPTH: Appx. same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT. OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUE REPORT OF: TEST WATER SHUT-OFF STRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON" (other)	(MOVEL Report results of multiple completion or zone
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly star	e all pertinent details, and give pertinent dates.
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine ARCO has plugged and abandoned the subject well Notice dated December 30, 1982, and approved by Injection interval 1457' - 1459', as per the attached plugging operations report Completed P & A, 6-30-83. Final restoration will be commenced as soon as subsequent report will be filed when restoration	l in accordance with the Sundry by the BLM-MMS on January 13, 1983 Gallup fm. Spotted cement plugs . weather permits. An additional on has been completed. APPROVED TO THE PLUGGING OF THE
	WELL BORE ONLY. LIABILITY UNDER THE BOND RETAINED UNTIL SURFACE

	WELL BORE ONLY. LIABILITY UNDER THE BOND RETAINED UNTIL SURFACE
Subsurface Safety Valve: Manu. and Type	RESTORATION IS COMPLETED AND APPROVED.
18. I hereby certify that the foregoing is true an	
SIGNED Stephen Rose	TITLE Dist. Prod. Supt. DATE November 30, 1983
L. Mark Hollia (This	space for Federal or State office use) TITLE ACTING AREA WANAGER DATE
CONDITIONS OF APPROVAL, IF ANY:	AREA WANAGER

HSG #217 Horseshoe Gallup Field

P & A OPERATIONS:

MI RJ 6/28/83. Unsuccessfully attempted to rel pkr. Acquired verbal approval to lse the pkr f/Mr. Howard Lemm, USGS, Grand Junction. Backed off @ top of pkr & pmpd 22.5 cf cmt slurry. PU ll jts & perf'd 2 holes using WL @ 1310'. Lwrd tbg to 1304', pmpd 30 sx cmt (36 cf) & unsuccessfully attempted bullhead sqz due to tbg vac. SDON. RIH w/sinker bar on WL; and could not find TOC across perfs. RIH w/tbg, sptd 28 sx cmt (34 cf) & bullheaded, OK, getting some fld back behind 4-1/2" csg. POH w/tbg. WOC f/4 hrs, RIH w/sinker bar on WL & tagged TOC @ 1226'. SDON.

RIH & perf'd 2 holes @ 155' & sqz'd perfs w/28 sx neat cmt. Will fin surf P & A @ later date. RD & MO.

FINAL REPORT - WELL P & A, 6/30/83.

Tag cmt plug @ 53'. Install dry hole marker @ surf w/ 3-1/2 sx cmt. RD & MO-CU 6/30/83.

CONDITIONS OF APPROVAL AND ADDITIONAL REQUIREMENTS

- 1. This Subsequent Report of Abandonment (SRA) is approved to the plugging of the well bore only. Liability under the bond is retained until surface restoration is completed and approved.
- 2. Once the dirt work has been completed, the operator will submit Form 3160-5, Sundry Notice, informing the Bureau of Land Management (BLM) of this operation. This Sundry Notice, or Second Subsequent Report of Abandonment (SSRA) will be an acceptance rather than an approval action. (Instruction Memorandum No. CO-87-417).
- 3. Form 3160-5, Sundry Notice, will be submitted when all restoration is completed. This Sundry Notice, or Final Abandonment Notice (FAN), will be submitted only when the site is ready for inspection by an official of the BLM.
- 4. PHASED RELEASE OF BOND LIABILITY After proper plugging of the leasehold's well(s), and after the site has been stabilized and seeded, a percentage of the bond liability can be released. Operators who wish to request partial liability release of a single lease bond may delay filing Form 3160-5, Second Subsequent Report of Abandonment (SSRA) until after the site has been reseeded. In this case, the Sundry Notice should not only detail work that was done but also request partial bond liability release. (Instruction Memorandum No. CO-87-307).