

			X

Indian Agency \_\_\_\_\_

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

...1-147-INS-7653

Allotted .....

**Lease No.** \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**October 30 19 59**

Well No. 342 is located 660 ft. from N line and 660 ft. from E line of sec. 36

(1/4 Sec. and Sec. No.)

**34** **17**  
(Twp.) (Range)

**AM PM**  
(Meridian)

**Underlined**  
(Field)

**San Juan**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is 5220 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6 1/2" hole to 1289'

Top of Dakota	1245'
Water at	1245'

**Plan to plug as follows:**

Cement plug from 1289 to 1200  
 660 to 600  
 90 to surface

**Had between plugs**

**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company **KING OIL COMPANY**

Address 745 Petroleum Club Bldg.

**Denver, Colorado**

By

Title President

U. S. GOVERNMENT PRINTING OFFICE 16-8437b-8