5. LEASE

UNITED STATES

DEPARTMENT OF THE INTERIOR	14-20-604-1950
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Yountain
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME Horseshoe Gallup Unit
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–0 for such proposals.)	8. FARM OR LEASE NAME
1. oil — gas —	Horseshoe Gallup Unit
well well other X - Injection	9. WELL NO. 186
ARCO OIL & Gas Co., Div. of	10. FIELD OR WILDCAT NAME
Atlantic Richfield Company 3. ADDRESS OF OPERATOR 707-17th Street,	Horseshoe Gallup Unit
P.O. Box 5540, Denver, CO 80217	11. SEC., T., R., M., OR BLK. AND SURVEY CR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit	AREA Sec. 35-31N-16W
AT SURFACE: 610' FNL & 2000' FEL, Sec. 35	12. COUNTY OR PARISH: 13. STATE
AT TOP PROD. INTERVAL: Appx. same	San Juan New Mexico
AT TOTAL DEPTH: Appx. same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	None Assigned
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KD8. AND WD) 5522' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	production and the second of t
TEST WATER SHUT-OFF FRACTURE TREAT	
SHOOT OR ACIDIZE	der our bund i incorporant
REPAIR WELL 🗍 🗎 🔀 💯 🖺 🖟	(NOTE: Report results of multiple completion or zone change on Form 9–330)
	thange on Form 9-330) 1383
MULTIPLE COMPLETE	x7
Character 201423	
ABANDON*	DIV.
DIST. 3	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is different and true vertical depths for all markers and zones pertinent.)	irectionally drilled, give subsurface locations and
ARCO has plugged and abandoned the subject well Notice dated December 30, 1982, and approved by	l in accordance with the Sundry y the BLM-MMS on January 13, 1983 Gallup fm. Spotted cement plugs
Completed P & A, 7-29-83.	
Final restoration will be commenced as soon as subsequent report will be filed when restoration	weather permits. An additional on has been completed.
Subsurface Safety Valve: Manu. and Type	APPROVED TO THE PLUGGING OF THE WELL BORE ONLY. LIABILITY UNDER THE BOND RETAINED UNTIL SURFACE RESTORATION IS COMPLETED AND APPROVED.
18. I hereby certify that the foregoing is true and correct	And the second s
SIGNED SIEPLEN ROSE TITLE Dist. Prod. Sup	Pt. DATE November 30, 1983
(This space for Federal or State off	5ca use) NOV 0 ₹ 1097
APPROVED BY L. Mark Hollis TITLE ACTING	DATE
CONDITIONS OF APPROVAL IF ANY: AREA MAN	AGER
AFFRUVED	
AS AMENDED	

. HSG #186, Horseshoe Gallup Field

P & A OPERATIONS:

MI & RU 7/28/83. Rel'd pkr & POH w/47 jts 2-3/8" tbg. LD pkr. RIH w/tbg OE. Spt 15 sx plug @ 1450'. PU 15 jts & press to 500 psi. SI & WOC. SDON.

FINAL REPORT - WELL P & A, 7/29/83!

Perfd 4 holes @ 1338'. Spt 30 sx plug & sqz'd 20 sx thru perfs. POH. Perf 2 holes @ 150'. Pmpd 30 sx plug dn 4-1/2" csg w/csg full of cmt dn to 150'. Cut off wellhd. Instl'd DH marker. RD

CONDITIONS OF APPROVAL AND ADDITIONAL REQUIREMENTS

- 1. This Subsequent Report of Abandonment (SRA) is approved to the plugging of the well bore only. Liability under the bond is retained until surface restoration is completed and approved.
- 2. Once the dirt work has been completed, the operator will submit Form 3160-5, Sundry Notice, informing the Bureau of Land Management (BLM) of this operation. This Sundry Notice, or Second Subsequent Report of Abandonment (SSRA) will be an acceptance rather than an approval action. (Instruction Memorandum No. CO-87-417).
- 3. Form 3160-5, Sundry Notice, will be submitted when all restoration is completed. This Sundry Notice, or Final Abandonment Notice (FAN), will be submitted only when the site is ready for inspection by an official of the BLM.
- 4. PHASED RELEASE OF BOND LIABILITY After proper plugging of the leasehold's well(s), and after the site has been stabilized and seeded, a percentage of the bond liability can be released. Operators who wish to request partial liability release of a single lease bond may delay filing Form 3160-5, Second Subsequent Report of Abandonment (SSRA) until after the site has been reseeded. In this case, the Sundry Notice should not only detail work that was done but also request partial bond liability release. (Instruction Memorandum No. CO-87-307).