(Formerly 9-331) DEPARTA	UNITED STATES MENT OF THE INTERIO U OF LAND MANAGEMENT	SUBMIT IN TRIPLICATES (Other Instructions on reverse aids)	Budget Bureau No. 1004-0135 Expires August 31, 1985  B. LEARE BERNATION AND BREIAL NO.
			14-20-603-734 6. IF IFFIAH, ALLOTTES OR TRIDS HAME
SUNDRY NOTICES AND REPORTS ON WELLS  (1/10 not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for each proposals.)			Navajo
OFL GAS OTHER I	njection		7. THIT MERRYSHT HAME
2. HAME OF OPERATOR	1136661011		Horseshoe Gallup Unit
ARCO Oil & Gas Company, Division of Atlantic Richfield Company			Horseshoe Gallup
1816 E. Mojave, Farmington, New Mexico 87401			9. WELL DO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirementa.  See also space 17 below.)  At ourface			10. PIBLO AND POOL, OR WILDCAT
			Horseshoe Gallup
			11. SEC. T. S. M., OS SLE. AND SURVEY OR AREA
620' FNL & 702' FWL			$1  \mathcal{V}$
14. PERMIT NO.	16. BLEVATIONS (Show whether Mr. E	· · · ·	Sec. 31, T-31N, R-16W
	5499' GR		San Juan NM
16. Check Ap	propriate Box To Indicate Na	ture of Notice, Report, or C	Other Data
			THE REPORT OF:
TEST WATER SHUT-OFF	TLL OR ALTER CIBING	WATER SECT-OFF	BEPATRING WELL
PRACTURE TREAT	ILLTIPLE COMPLETE	PRACTURE TREATMENT	ALTERING CARING
<del></del>	BANDON*	SHOOTING OR ACIDIZING	VSTHOOMMENT.4
(Other)	HANGE PLANE	(Other)	of multiple completion on Well etion Report and Log form.)
economically operate the CO2 flooding for the Ho tional oil recovery(a C the study to assess CO2 the workover of existing proposes that this well bore will be available,	y respectfully reques t this time, under the subject well. An overseshoe Gallup Field O2 Pilot Project is perflooding potential). If yells, and the drill be maintained in the should it be needed	ts approval for exte e current waterflood ngoing study to dete is underway, which m lanned to begin late Implementation of ling of new wells. long term shut-in s as part of a future	ension of long term shut-in loperation, ARCO cannot ermine the feasibility of may yield significant addition this year as part of a CO <sub>2</sub> flood would require For this reason, ARCO status so that the well-
	THIS ACTIONS OF		<b>199</b>
			The state of the s
18. I hereby certify that the foregoing in	true and correct		
SIGNED Den 4. Den	TITLE Pro	duction Supervisor	DATE 6/24/88
(This space for Federal or State offic	e zee)		24 W
APPROVED BY	TITLE	4	- Della

"- "See Instructions on Reverse Side