

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP 077692
Unit East

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ May 19_____, 19____

Last _____

Well No. _____ is located _____ ft. from _____ line and _____ ft. from _____ line of sec. 26

_____ Section 26 _____

($\frac{1}{4}$ Sec. and Sec. No.) _____ (Twp.) _____ (Range) _____ (Meridian)

_____ Basin Dakota _____ San Juan _____ New Mexico _____


(Field) _____ (County or Subdivision) _____ (State or Territory)

The elevation of the derrick floor above sea level is 5922 ft. **O. L.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth-7049 P.B.T.D.- 7017
 Ran logs: top of Pictured Cliffs-2348, Cliff House-3900, Point Lookout-4622
 Gallup-5950, Greenhorn-6690, Graneros-8750, Dakota-6865
 Perforated 6870-6908 with 4 shots per ft.
 Ran 220 jts., 7038' of 4 1/2" casing, landed at 7049 with 485 sf.
 D.V. tool-5007
 Tested 2 hrs., with 500# pressure. Pipe Chay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Aztec Oil and Gas Company

Address Driver # 570

ORIGINAL SIGNED BY JOE C. SALMON

Marlington, N.H.

By _____ Joe C. Salmon
Title District Superintendent