

		0
Sec.	23	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Ute Indian Agency
Lease No. Ute Mountain
Unit Tribal Contract
No. 14-20-604-123

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 1, 19 57

Well No. 1/ Ute-Indian is located 420 ft. from N line and 1980 ft. from E line of sec. 23
NW/4 NE/4 Sec. 23 31N 15W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5761 ft. DF

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- Well was spudded 11-23-56. 96' of 9 5/8" Casing cemented with 100 sacks regular cement on 11-25-56. Drilled plug and tested with 500# pressure on 11-26-56.
- Cemented 2649' of 5 1/2" Casing with 100 sacks regular on 12-10-56.
- Perforated well w/232 shots 2534-2592 ft. Acidized with 500 gallons of Mud Acid 2534-2592 12-17-56. Sand-Oil Frac. thru perforations with 25,956 gallons Oil and 25,000# sand. BDP 1200#, I.R. 52.5 bpm on 12-20-56.
- Ran 2555' of 2 3/8" 4.7# Tubing on 12-27-56.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southern Union Gas Company

Address Burt Building

1700 Patterson St.

Dallas, 1, Texas

By Paul J. Blate

Title Drilling Superintendent