

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. 14-20-604-82
2. NAME OF OPERATOR H. M. Galloway		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Mtn. Indian
3. ADDRESS OF OPERATOR 101-2 Petroleum Plaza Bldg., Farmington, N.M. 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1810' ISL, 620' FWL		8. FARM OR LEASE NAME Ute Indian I
14. PERMIT NO.		9. WELL NO. 6
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3347' GR		10. FIELD AND POOL, OR WILDCAT Verde Gallup Ext.
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T31N, R14E
		12. COUNTY OR PARISH San Juan
		13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Reason: well will not produce oil in commercial quantities.

Spot cement plug in Gallup open hole zone and continue 50' up inside of 4½" casing. Shoot off 4½" casing @ 1280'. Spot 50' cement plug across shooting point. Spot 50' of cement across bottom of surface casing. Spot 10 sacks of cement in top of hole and erect dry hole marker.

RECEIVED

OCT 20 1972

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

18. I hereby certify that the foregoing is true and correct

SIGNED

H. M. Galloway

TITLE

Operator

DATE

Oct. 18, 1972

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

H. M. Galloway