F /m (160-5)

UNITED STATES

SUBMIT IN TRIPLICATES

Budget Bureau No. 1004-0135 Expires August 31, 1985

	omerly 9=331) DEPARTMENT OF THE INTERIOR (Other Instructions on Figure 1983) BUREAU OF LAND MANAGEMENT	3. LEASE DESIGNATION AND SEELAL NO. I-149-Indian-7652
	SUNDRY NOTICES AND REPORTS ON WELLS (Ito not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTES OR TRIBE NAME Navajo
Ī.		7. UNIT AGEREMENT NAME
	WELL GAB WELL OTHER Water Injection Well	Horseshoe Gallup Unit
2.	NAME OF OPERATOR	8. PARM OR LEASE HAME
	ARCO Oil & Gas Company, Division of Atlantic Richfield Co.	Horseshoe Gallup Unit
3.	ADDRESS OF OPERATOR	9. WELL NO.
	1816 E. Mojave, Farmington, New Mexico 87401	67
1 .	LOCATION OF MELL Report location clearly and in accordance with any State requirements.* See 1150 space 17 below.)	10. FIELD AND POOL, OR WILDCAT
	At surface	Horseshoe Gallup
		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
	660' FNL & 660' FEL Unit A	Sec. 15, T-31N, R-17W
14.	PERMIT NO. 15. BLEVATIONS (Show whether OF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	5251' GL	San Juan NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBBRQUENT REPORT OF:		
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	:	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE		ABANDON*	i	SBOOTING OR ACIDIZING	ABANDONMENT [®] X
REPAIR WELL		CHANGE PLANS		(Other)	
Irben)			(Nors: Report results of mi Completion or Recompletion	ultiple completion on Well Beport and Log form.)	

17 belowed to complete operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and (rue vertical depths for all markers and sones pertinent to this work.)

This well was plugged 6/5/89 - 6/7/89 as follows:

Plug	<u>Interval</u>	Cement	<u>Notes</u>
1	800-900	30 sx	Spotted cement to cover Gallup perfs 876'-890'.
	0-800		Circulated 9 lb. mud to surface.
2	0-176	48 sx	Perforated casing at 176' and circulated cement to surface.

Welded a steel plate over the top and installed a dry hole marke Casing left in hole: Casing Size 8-5/8" 28# J-55 5-1/2" 15.5# J-55

Surface cleanup was completed. Reseeding will be done per BLM specifications between July 1 and September 1, 1989.

		APP
18. I hereby certify that the foregoing is true and correct signed struct Mullicas	TITLE Production S	upervisor DATE 6/28/89
(This space for Federal or State office use)		JUL 1 n 1900
APPROVED BY	TITLE	Ken Townsend
Approved as to otherway of the cost base. Liability und it bond to control out!! Surface restoration to some, decad.	See Instructions on Revene Side	FOR AREA WAS ASSA FARMINGTON RESOURCE ASSA
	and illustrations on Health and Grad	