## STATE OF NEW MEXICO OIL CONSERVATION COMMISSION

SUBMIT IN TRIPLICATE TO DISTRICT OFFICE

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Senta Fe
Lease No	078040 "a"

Unit\_\_\_\_

Childers #1

RECEIVED

				150 2 0 405
SUND	RY NOTICES	AND REPO	ORTS ON WEL	LS EB 3 8 195
			REPORT OF WATER SHUT-OFF	Con con a
	RILL	1 11	REPORT OF SHOOTING OR ACIDE	TING
	HANGE PLANS	l il	REPORT OF SHOOTING OR ACIDIN	
	EST WATER SHUT-OFF		REPORT OF REDRILLING OR REP	AIR
	E-DRILL OR REPAIR WELL	·	REPORT OF ABANDONMENT	
	HOOT OR ACIDIZE	- I	RY WELL HISTORY	t t
	ULL OR ALTER CASING	i II		1 1
NOTICE OF INTENTION TO	BANDON WELL			
(INDIC	CATE ABOVE BY CHECK MA		, NOTICE, OR OTHER DATA	
		Febr	u <b>ary</b> - <del>2</del> 7	, 19 <u></u> ç
			•	
ell No. 1 Childer	s is located _890_ft	$from \frac{1}{1S}$ line and	1_1650_ft. from   li	ne of sec
(14 Sec. and Sec. No.)	31!\ (Twp.)	(Range)	(Meridian)	
Blanco-La Plata	San	Juan_County	New Mex (State of T	ie <del>o</del>
(Field)	(C	ounty or subdivision)	(Dears or x	
he elevation of the	derrick floor above se			
		TAILS OF WOR		
State names of and exp indicate	pected depths to objecti muddling jobs, cementin	ve sands; show sizes ng points, and all oth	, weights, and lengths of per important proposed wo	oroposed casings; ork)
	with 698 ats. n	itro glycerine	52 from 5053 to 53 . Well tested 198 hours after shot.	18 Vcf.
	Running Tubing.			
I understand that to		receive approval i <b>n v</b>	writing by the Geological	Survey before
Company	South rn Union	Cas Company		***************************************
Address	27 Oly Burt Build	ling		,
	Dallas, Texas	•	By # C >>>0	Agenury.
	-		Tela Drilling Sumer	