TONEY ANAYA GOVERNOR

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO 8RAZOS HOAD AZTEC, NEW MEXICO 87410 (505) 334-61713

December 21, 1984

Mr. James Smith Southland Royalty Co. P.O. Drawer 570 Farmington, NM 87499

Re: Patterson A Com #1 O-2-31N-12W

Dear Smitty:

The 1984 packer test on the referenced well was inconclusive. Please reschedule and retest the well in such a manner as to prove zone separation. Shut both zones in for a minimum of three days. Blow the higher pressured zone to the atmosphere for as long as it takes to get a significant pressure drop.

Advise this office at least 24 hours prior to the test, so we may provide a witness.

Yours truly,

Charles Gholson

Deputy Oil & Gas Inspector

CG/dj

cc: Well File

Operator File