Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

to Appropriate District Office	Ell	ergy, wimerars a	nu Naturai Ke	sources Department		Reviseu 1	-1-07
DISTRICT I P.O. Box 1980, Hobbs,	NM 88240			DIVISION	WELL AP	1 NO.	· · · · · · · · · · · · · · · · · · ·
P.O.Box 20			P.O.Box 2088		WEEE AL	3004511142	
P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088					5. Indicate	Type of Lease	(V)
DISTRICT III 1000 Rio Brazos Rd., Az	ztec, NM 8741()			6. State O	STATE Lil & Gas Lease No.	FEE X
,					0,000	n ce cus pease 1401	
		TICES AND REP					
•	ERENT RESER	VOIR. USE "APPI	LICATION FOR F	EN OR PLUG BACK TO PERMIT"	7. Lease 1	Name or Unit Agreement Na	ame
1. Type of Well:	(FORM C	:-101) FOR SUCH	PROPOSALS.)	2		LEEPER GAS COM	
OIL	GAS WELL	OTHER					
2. Name of Operator			Attention:		8. Well N	o.	<u>.</u>
Amoco Production C 3. Address of Operator	Company		D. I	CALAHAR		1	·····
•	enver	Colorado	80201	(303) 830-404	o 9. Pool na	me or Wildcat BLANCO-MV	
4. Well Location	. 12/	10	Cauth		700! -	10/	
Unit Letter	<u>L</u> :	Feet From The		Line and	/90 Fe	et From The Wes	Line
Section	34	Township	32N F	Range 10W	NMPM	SAN JUAN	County
		10. Elev	ration (Show wheth	her DF, RKB, RT, GR, etc	c.)		
11.	Check An	nropriate Boy	to Indicate	Nature of Notice,	Report or	Other Data	
NO		ENTION TO:	to marcate i		- '	IT REPORT OF:	
PERFORM REMEDIAL W			ANDON [
PERFORM REMEDIAL W	/URK	PLUG AND ABA	INDON [REMEDIAL WORK		ALTERING CASING	_
EMPORARILY ABAND	ON [CHANGE PLANS	s <u> </u>	COMMENCE DRILLI	NG OPNS.	PLUG AND ABANI	DONMENT [
PULL OR ALTER CASIN	G 📗			CASING TEST AND	CEMENT JOB		
OTHER:	 			OTHER:	CATHOD	IC PROTECTION	[
		rations (Clearly state	e all pertinent deta	ils, and give pertinent da	tes, including esti	mated date of starting any p	roposed
work) SEE RULE 11	l 03 .					MERCIT	
SEE ATTACHMEN	IT FOR PROC	EDURE.				MERCE	Total Control
						NOV 8 199	13
						OIL CON.	نا۷.
						, DIST. 3	
			,		`		
15 VOI 114 VE 4 N		0 0 5405 004	TAOT DALLA		5400		
IF YOU HAVE AN	Y QUESTION	S, PLEASE CON	TACT DALLAS	S KALAHAR AT (303	3) 830-5129.		
I hereby certify that the	information abov	/e is true and comple	te to the best of n		•		
SIGNATURE A	alas	as/D	m	TITLEBUSINES	S ANALYST	DATE 11-01	-1993
TYPE OR PRINT NAME	DA	ALLAS KALAHA				TELEPHONE NO. (30	3) 830-512
(This space for State Use	e)						
open tot smis on	7			DEPUTY OIL & GA	IS INSPECTOR	DIST #3	0 100-
APPROVED BY ORIGIN	AL SIGNED B	Y ERNIE BUSCH	<u></u>	TITLE	TO HESE LUICIN,	DIST. * DATNOV	<u>- 9 1993</u>

LEEPER GAS COM #1

MIRUSU. DIG PITS. CMT CSG. INSTALL DIVERTER. TIH W/ WASH PIPE & HIT CMT @ 8' BELOW COKE BREEZE ABOVE. HIT GRAVEL @ 15'. JET OUT TO 20'. TOH. TIH W/ 1/2 MULE SHOE TO 20'. JET OUT GRAVEL TO 35'. WORKED PIPE TO GET BELOW 35'. LOST CONTROL ON 4 WIRES. TOH. PULL 6" PVC CSG 8'. TIH. DRL OUT TO 10'. OLD HOLE VERY CROOKED. SET 8-5/8 CSG TO 10'. CMT TOP & BTM. TIH W/ 6-1/4 BIT TO 20'. HIT ROCKS & DRL TO 26'. PU TO CLEAN HOLE & LOST 6' OF HOLE. MIRU CABLE TOOL RIG. DRIVE 7" CSG DWN TO 41' OVER 10 DAYS. DRL TO 45'. MIRUSU. SET RIG OVER HOLE. CMT OFF CSG. WELD TREADS ON. TIH W/ BIT TO 42'. C/O TO 151'. DRL UP 3 ANODES PVC & COKE BREEZE. TIH W/ AIR HAMMER. DRL OUT FROM 151-250'. DRL OUT 5 ANODES. TOH. TIH W/ AIR HAMMER. C/O FROM 250-300'. DRL OUT 2 ANODES. TOH. RDMOSU. RU COIL TBG UNIT & RIH TO 300'. PMP 70 SX CMT TO SURF. RDMO COIL TBG UNIT. RIH W/ TAPE & TAG. CMT @ 40'. FILL HOLE W/ CMT. INSTALL MARKER. CLEAN LOCAATION & BACK FILL PIT.