

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-045-21634
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B 10938
7. Lease Name or Unit Agreement Name	STATE COM J
8. Well No.	6A
9. Pool name or Wildcat	PICTURED CLIFFS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator CONOCO INC	
3. Address of Operator 10 Desta Drive STE 100W. Midland, TX 79705	
4. Well Location Unit Letter <u>O</u> : <u>850</u> Feet From The <u>SOUTH</u> Line and <u>1680</u> Feet From The <u>EAST</u> Line Section <u>36</u> Township <u>31 N</u> Range <u>9 W</u> NMPM <u>SAN JUAN</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 6366	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: <u>OIL CON. DIV</u> ☐ <u>DIST. 5</u> ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: <u>DUAL W/ MESAVERDE</u> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-23-92 MIRU. SET ANCHORS. CLEAR SNOW FROM LOCATION. KILL WELL W/ 35 bbl 2% KCL. RIH W/ 7" BIT & SCRAPER TAGGED TOP OF LINER @ 3239'. POOH. PUMP 25 bbl KCL TO CALM WELL. RIH W/ 4 1/2" BIT & SCRAPER, TAGGED FILL @ 5638'. POOH. RIH W/ 4 1/2" RBP SET @ 3350'. SPOT SAND ON RBP. TAGGED TOP OF SAND @ 3337'. POOH. RUN GR, CCL. GIH W/ 2 SPF PERF GUN. 120 PHASING. PERF FROM 3188 TO 3204. POOH. RIH W/ BAKER SAP TOOL W/ 24" ELEMENT & 50 STANDS 2 7/8" WORKSTRING TO 3070'. BREAKDOWN PERFS (16 SETS, 2 FT PER SET) W/ 2 bbls 15% HCL PER SET @ 1 BPM. RIH TAG TOP OF SAND @ 3337'. CLEAN OUT 13" OF SAND. LATCH ON RBP. POOH. RIH W/ BAKER MODEL "D" PACKER SET @ 4850'. POOH. RIH W/ 1.9" J-55, 2.76# TBG TO 5673' (FOR MESAVERDE PROD.). 12-31-92 SHUT DOWN WORK ON PICTURED CLIFFS UNTILL WEATHER CLEARS. 3-31-93 RU WESTERN TO FRAC PC. FRAC PC FERFS 3172-3204. DUMMY PAD 9996 gal 20# LINEAR GEL AT 19 bpm, AVG PRESS 3180#. PUMPED 12,000 gal CLEAN N2 FOAM PAD W/ NO SAND. PUMPED 12,000 gal N2 FOAM W/ 51,300# 16/30 SAND, AVG RATE 19 bpm, AVG PRESS 3100#. 4-1-93 RDMO. WELL FLOWING. 4-3-93 WELL TESTED 140 MCF IN 24 HRS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE SR REGULATORY SPEC. DATE 4-5-93
TYPE OR PRINT NAME BILL R. KEATHLY TELEPHONE NO. 915-686-5424

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE APR 8 1993
CONDITIONS OF APPROVAL, IF ANY: