MIT IN TRIPLICATES	Form approved. Budget Bureau No. 42-R1
her instructions on re-	5. LEASE DESIGNATION AND SERIAL N

DATE _

Form 9-331		UNITED STATE	£5	(Other instructions on		eau No. 42-E1424.	
(May 1963)	DEPAR	TMENT OF THE	INTERIC	OR verse side)	5. LEASE DESIGNATION	N AND SERIAL NO.	
GEOLOGICAL SURVEY					SF-078040-A		
		6. IF INDIAN, ALLOTT	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
9	SUNDRY NO	OTICES AND REF	OKIS C	JIN WELLS			
(Do not us	e this form for pro Use "APPI	oposais to drill of to deep LICATION FOR PERMIT—	" for such pro	nck to a different reservoir. oposais.)			
1.					7. UNIT AGREEMENT ?	MAME	
OIL G	AS OTHE	R					
2. NAME OF OPERATOR					8. FARM OR LEASE NA	8. FARM OR LEASE NAME	
Aztec Oil & Gas Company					Childers	Childers	
8. ADDRESS OF OPI	ERATOR	9. WELL NO.	9. WELL NO.				
P. O. Dra	awer 570, F	armington, New M	Mexico_	87401	#1-A		
4. LOCATION OF WI	кии (Report locatio	on clearly and in accordan	ce with any S	State requirements.*	10. FIELD AND POOL,	10. FIELD AND POOL, OR WILDCAT	
At surface		90' FSL & 1070'	FEL			Blanco Mesa Verde	
		ection 1, T31N,			SURVEY OR ARE	SURVEY OR AREA	
`	`				Continu	Continua 1 TZ1N D11W	
		15. ELEVATIONS (Sho	w whather DF	PT (R etc.)	12. COUNTY OF PARIS	Section 1, T31N, R11W	
14. PERMIT NO.				ar, any cour,	San Juan	New Mexic	
			50' GR			1 New Mexic	
16.	Check	Appropriate Box To	Indicate N	ature of Notice, Report, or	r Other Data		
	NOTICE OF I	NTENTION TO:	ſ	SUBS	EQUENT REPORT OF:		
	<u> </u>			WATER SHUT-OFF	REPAIRING	WELL	
TEST WATER S		PULL OR ALTER CASING MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING	ALTERING CASING	
FRACTURE TRE		ABANDON*		SHOOTING OR ACIDIZING		ABANDONMENT*	
SHOOT OR ACII		CHANGE PLANS		(Other)	CASING REP		
(Other)	L			(Nore: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
	OSED OR COMPLETED	OPERATIONS (Clearly state	all pertinent	2 to 1 de mentione de	tes including estimated d	ate of starting any	
proposed wo	ork. If well is di	rectionally drilled, give sub	surface locati	i details, and give pertinent da- ions and measured and true ver	tical depths for an above	ore and sound per or	
				_			
8-19-76	Ran 78 Jos	ints Of 7" 23# K	(-55 Inte	ermediate Casing, S	hoe Set At 3110	' KKB 6	
	Eleat Col	UI 65/35 Class	65/35 Class b, 12x				
	Gel & 1/4	lowed by 70 Sac	owed By 70 Sacks Of				
	Class "B"	lass "B" & 2% CaCl. Plug Down.					
		. 00 41 11 10 5	-0# V FF	Casing Sat Shoe 8	Float Collar A	at 5390'.	
8-23-76	Ran 58 Jos	Ran 58 Joints Of 4½" 10.50# K-55 Casing, Set Shoe & Float Collar At 5390', Top Of Liner Set At 2965'. Cemented With 20 Barrels Of Gel Water & 240 Sacks					
	Top Of Lin	Class "B" With 4% Gel, 1/4 Cubic Feet Of Fine Gilsonite Per Sack & .6%					
	Of Class	"B" With 4% Gel,	, 1/4 Cu	DICTECT OF TIME OF	.1301120	•	
	D-19. Plu	g Down.	4.5				
					1	· .	
				. 1	l'ancoma .		
				!			
				į	AUG 9.6 191	76	
				:		د بيده	
					U.S. GERMANIAN	URVEY Å	
					U.S. GEN COMME	k k	
				.*			

TITLE

(This space for Federal or State office use)

District