

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Amoco Production Company		8. Farm or Lease Name Valentine Gas Com "C"
3. Address of Operator 501 Airport Drive, Farmington, N. M. 87401		9. Well No. 1
4. Location of Well UNIT LETTER E 1450 FEET FROM THE North LINE AND 790 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 32N RANGE 10W N.M.P.M.		10. Field and Pool, or Wildcat Blanco Pictured Cliffs
15. Elevation (Show whether DF, RT, GR, etc.) 6107' GL		12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JCB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Spud & Set casing

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 12 1/4" hole on 4/19/77. Drilled to 253' and set 8 5/8" K-55 casing at 253' with 250 sacks Class B 2% Ca Cl₂. Circulated out 20 sacks good cement. WOC and pressure tested casing to 500 PSI, OK. Drilled 7 7/8" hole to TD 3070. Set 4 1/2" K-55 casing at 3070' with 730 sacks Class B 50:50 Poz, 6% Gel, 2 pounds medium Tuf Plug per sack followed with 100 sacks Class B Neat. Circulated out 30 sacks good cement.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *E. J. Servadea* TITLE Area Adm. Supvr. DATE May 3, 1977

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: