

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR
El Paso Natural Gas Company

3. ADDRESS OF OPERATOR
Box 990, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1765' N, 1500' W
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF ☐	☒
FRACTURE TREAT ☐	☒
SHOOT OR ACIDIZE ☐	☐
REPAIR WELL ☐	☐
PULL OR ALTER CASING ☐	☐
MULTIPLE COMPLETE ☐	☐
CHANGE ZONES ☐	☐
ABANDON* ☐	☐
(other) _____	

5. LEASE

NM010989

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fields Com

9. WELL NO.

5A

10. FIELD OR WILDCAT NAME

Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T-32-N, R-11-W
N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6340' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-4-77 T.D. 3429'. Ran 80 joints 7", 20#, K-55 intermediate casing, 3417' set at 3429'. Cemented with 515 cu. ft. cement. W.O.C. 12 hours, held 1200#/30 minutes. Top of cement at 3025'.

8-7-77 T.D. 5724'. Ran 60 joints 4½", 10.5#, K-55 casing liner, 2463' set 3261-5724'. Float collar set at 5706'. Cemented with 425 cu. ft. cement. WOC. 18 hrs.

12-7-77 P.B.T.D. 5706'. Tested casing to 3500#, O.K. Perfed C.H. 4573-81, 4630-34, 4665-85, 4717-34, 4810-30' w/16 SPZ. Fraced with 54,000# 20/40 sand and 54,000 gallons water. Dropped 4 sets of 16 balls each. Flushed with 6420 gallons water. Perfed Men. 4867-75, 4888-94, 4904-22, 4922-40, 4941-58, 5039-63, 5103-09, 5158-70 w/16 SPZ. Fraced with 83,000# 20/40 sand and 83,000 gallons water. Dropped 7 sets of 16 balls each. Flushed with 6620 gal. water. Perfed upper P.L. 5307-22 5322-37, 5356-62, 5372-80, 5404-14, 5425-38, 5451-58, 5458-72' w/16 SPZ. Fraced with 81,000# 20/40 sand and 88,800 gallons water. Dropped 5 sets of 16 balls

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft. (_____)

18. I hereby certify that the foregoing is true and correct

SIGNED A. P. Duce TITLE Drilling Clerk DATE 12-9-77

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

*See Instructions on Reverse Side

RECEIVED

DEC 13 1977

U.S. Geological Survey
Farmington, N.M.

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1976 O - 214-149

each. Flushed with 6910 gals. water. Perfed lower P.L. 5503-09, 5550-56, 5583-93, 5605-17, 5629-37, 5647-54, w/14 SPZ. Fraced w/35,000# 20/40 sand and 35,120 gallons water. Dropped 3 sets of 14 balls each. Started flush, well sanded off after 3000 gallons of flush in.