ર્ક કો 60-5 ---- કો 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-C
Expires: March 31, 1993

SUNDRY NOT Do not use this form for propo Use "APPLICA	5. Lease Designation and Serial No. SF-078604 6. If Indian, Allottee or Tribe Name			
		7. If Unit or CA, Agreement De	signation	
1. Type of Well Oil Well Well Well Other		8. Well Name and No.		
2. Name of Operator	Attention:		Scott LS 3A	
Amoco Production Company	Dallas Kalahar	9. API Well No.		
3. Address and Telephone No.		3004522755		
P.O. Box 800, Denver, Colorado 80201		10. Field and Pool, or Exploratory Area		
4. Epication of Well. (Foctage, Sec., T., R., M., or Survey Description)		Blanco Mesaverde		
1800' FSL 1090' FEL	Sec. 29 T 32N R 10W	11. County or Parish, State San Juan	New Mexico	
) San Juan	New Mexico	
12. CHECK APPROPRIA	ATE BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER [DATA	
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intert Subsequent Report Final Abandon/nent Notice		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water or results of multiple completion on Report and Log form.)	Well Completion or	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work . If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PECEIVED
FEB1 1 1994
OIL CON. D'''

94 JAN 27 PH 1: 28 070 FARMINGTON, NM

	Dist.		
14. I hereby certify that the foregoing is true and correct Signed Signed	Title _	Staff Business Analyst Date 1/24/94	
(This space for Federal or State office use)		ACCEPTED FOR RECORD	
Approved byConditions of approval, if any:	Title -	FEB 08"1994	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to representations as to any matter within its jurisdiction.	make to any department	t or egency of the United States SEARMINGTON, DISJRICH DEFICE	
* See	Instructions on F	Reverse Side	

SCOTT LS #3A

12/03/93 MIRUSU. TOH W/PMP & RODS, BROKE DN PMP, PMP SCREEN SCALED OFF - BAD SCALE ON PMP PARTS. RU HOT OIL TRUCK PMP 30 BBLS DN TBG, TIH W NEW PMP, REPLACED STUFFING BOX RUBBERS, PRESS TST PMP TO 500 PSI, HUNG WELL ON, HAD GOOD PMP ACTION.

CHECKED PMP ACTION, PMP WOULD NOT, PRESS UP TO 260 PSI. WOULD NOT INCREASE, LONG STROKED PUMPED NO INC. - PULLED ROD & PMP. MOVE IN BLOW TANK & HOOK UP LINES, BLED OFF PRESS, ND WH NUBOP RELEASE TBG ANCHOR, TIH & TAG TIH FOR FILL @ 5695 - 29 FT. FILL, TOH W/TBG, TIH W/3 7/8 BIT & SCRAPER TO 5695, TOH W/50 STDS.

SITP=0 SICP=320 PSI BLED OFF PRESS, TOH W/SCRAPER, PMP 60 BBLS, TIH W/35 JTS 2 3/8 TBG PKR & TBG TESTER, SET PKR @ 4507 FT. TAIL PIP @ 5622, FLOWED TBG TESTER & FILLED W/16 BBLS & PRESS TST TO 2000 PSI. OPEN TESTER & PMP 660 GAL OF P 38 & DISP W/22 BBLS, 4 BPM @ 350 PSI, SHUT WELL IN FOR 24 HR SOAK.

SITP=0 RU ACID EQUIP, PMP & DISPLACE 1875 GAL OF 15% HCL @ 1.5 BPM EVERY 2 MIN & DISPLACE W/21 BBLS WATER, SWI FOR 1 HR, RU TO SWAB RIH & STUCK TOOLS @ 1700 FT. PULLED LOOSE & ROH W/TOOLS & PARAFFIN, RU HOT OIL TRK & PMP 30 BBLS HOT OIL DN TBG, RU TO SWAB, IFL=4500 FT. MADE 7 RUNS REC 8 BBLS, RD SWAB, RELEASED PKR & TOH.

SITP=250 SICP=340, PMP 15 BBLS WATER, TOH W/PKR & TBG TESTER, TIH W/1/2 MULE, 1 JT, SN, 35 JTS, ANCHOR, TIH & TAG FILL @ 6592, TOH & LAND TBG @ 5659 KB, NDBOP NUWH, RU TO SWAB, IFL=4500 FT, MADE 20 RUNS REC 68 BBLS, SICP=340 PSI, WELL WOULD NOT FLOW.

SICP=340, SITP=SLIGHT BLOW, RU TO SWAB, IFL=4500 FT, MADE 6 RUNS REC 22 BBLS, WELL STARTED TO FLOW ON 2 INCH OPEN, GETTING OIL ACID & WATER. FLOW WELL OVER WEEKEND FOR 42 HRS, ON 2 INCH OPEN SICP=320, FTP=19 SPI, RECOVERED 91 BBLS.

SICP=300 PI, FTP=26 ON 2 INCH OPEN RIGGED UP & PUMPED 40 BBLS W/3BBLS OF WA, 8280 DN TBG, ADN DISPLACED W/30 BBLS, TIH W/PMP & ROD S, PMP STACKED OUT ON PRAFFIN W/35 RODS, RU & PUMPED 30 HOT OIL DN TBG, RIH W/PMP & RODS, SEATED & SPACED OUT & PRESS TEST TO 500 PSI & HELD OK, HUNG WELL ON. CHECKED PMP ACTION & PRESS UP W/ROD PMP TO 500 PSI. RDMOSU 12/15/93.

12/22/93 MOVED ON RIG, RE-SPACED OUT PMP & RESEATED, PUMPED UP & PRESS TEST TO 500 PSI, HELD OK, LEFT WELL PUMPING OVER HOLIDAYS. CHECKED PMP ACTION, RIGGED DOWN MOVE OFF SERVICE UNIT 12/27/93.