(June 1990) DEPARTME		D STATES OF THE INTERIOR ND MANAGEMENT	PORM APPROVED Budget Burneu No. 1004-0135 Expires: March 31, 1993 3. Lesse Designation and Serial No.
Do not use this for	SUNDRY NOTICES AN m for proposals to drill d	ND REPORTS ON WELLS for to deepen or reentry to a different ret ERMIT—" for such proposals	SF078707
	SUBMIT IN	TRIPLICATE	7. If Unit or CA, Agreement Designation
I. Type of Well Oil Well XWell 2. Name of Operator Snyder Oil	N/A 8. Well Name and No. DUKE #1M 9. API Well No.		
3. Address and Telephone No.         P.O.       2038         4. Location of Well (Pootage, 1640' FSL &	2364800 10. Field and Pool, or Exploratory Area Basin Dakota/Blanco 11. County or Parish, State		
12 CHECK AF	PPROPRIATE BOX(s) 1	O INDICATE NATURE OF NOTICE,	San Juan County, NM REPORT, OR OTHER DATA
	TYPE OF SUBMISSION TYPE OF ACTION		······································
Notice of Is		Abandonment Recompletion Plugging Back Casing Repair	Change of Plans Change of Plans New Construction Non-Rowtine Fracturing Water Shut-Off
	Sonment Notice	Altering Casing	Conversion to Injection  Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form )  e of starting any proposed work. If well is directionally drilled,
DUE TO THE U THE DAKOTA 2	JNECONOMICAL NAT ZONES WILL BE AE DWING ATTACHMENT	WELL IN THE MESA VERDE AL TURE OF THE PRODUCTION. BANDONED AND THE PROPOSED C. WORK WILL PROCEED AS	THE MESA VERDE AND PROCEDURE IS STATED
11-15-93, ar	pproved on Dec 2	s to supersede Approve Su 27, 1993.)	
AL <i>N</i> I'	<b>GEIVE</b> N 2 8 1994	SEE ATTACHED FOR CONDITIONS OF APPROVAL	91 JAH 21 - MILE 070 FARMINGTON, NM
	CON. DIV DIST. 3		
14. I hereby certify that the form Signed	Late office use)	CONSULTING ENGINE 	
Approved by Conditions of approval, if an	y:	Table	APPROVED
Title 18 11 5 C. Section 1001		nely and willfully to make to any down	he United States and 1914, Activity of Iraudulent statements

í

SNYDER OIL CO.

----

November 9, 1993

## Duke #1M (MV/Dk) SE, Sec. 13, T31N, R13W San Juan County, New Mexico

## PLUG AND ABANDONMENT PROCEDURE:

\* H2S 160 ppm \*

- MOL and RUSU. Comply to all NMOCD, BLM and Snyder safety rules and regulations. Install H2S monitoring and safety equipment; review safety procedures. Blow well down; kill with water if necessary; a 8.3 ppg wellbore fluid exceeds the exposed reservoirs' pressure. ND wellhead and NU BOP and stripping head; test BOP.
- 2. NU offset spool; POH with 1-1/4 Mesaverde tubing and LD; change over for 1-1/2" tubing; release seal assembly from Baker Model D packer at 6620'; POH with 1-1/2" Dakota tubing and LD.
- 3. PU 5-1/2" cement retainer, 2" work tubing string and RIH; set at 6600' (above Dakota perfs); establish rate into perfs. Plug #1 under CR at 6600' to 6890' with 72 sxs Class B cement (100% excess), squeeze 66 sxs below CR then spot 6 sxs on top. POH to 5866'.
- Plug #2 from 5866' to 5766' with 17 sxs Class B cement (top Gallup at 5816'). POH with setting tool.
- 5. PU 5-1/2" cement retainer and RIH; set at 3650' (above Mesaverde perfs and top); establish rate into perfs. Plug #3 under CR at 3650' to 4776' with 196 sxs Class B cement (long plug, 50% excess), squeeze 190 sxs below CR then spot 6 sxs on top. POH to 3500'. Load well and circulate clean. Pressure test casing to 500#. POH with setting tool.
- 6. Perforate 4 holes at 2161' (below PC top at 2111'); establish rate into holes. PU 5-1/2" cement retainer and RIH; set at 2100'; establish rate into holes. Plug #4 under CR at 2100' from 2161' to 1705' with 134 sxs Class B cement outside casing (100% excess, covers Ft top), and 17 sxs inside casing from 2161' to 2061'. POH to 1805'.
- Plug #5 from 1805' to 1705' with 17 sxs Class B cement inside casing (covers Ft top). POH to 309'.
- Plug #7 from 309' to surface with approximately 35 sxs Class B cement inside casing, circulate good cement to surface. Shut in well and SDFN.
- 10. ND BOP and cut off wellhead below ground level and install dry hole marker. RD and MOSU. Restore location.





• • •

## UNITED STATES DEPARTMENT OF THE INTERIOR

.

BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 1235 La Plata Highway Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 1 M Duke

•

## CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.

3. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 7:45 a.m. to 4:30 p.m.