State

Perm 9-331 (May 1963)	UNITED STA DEPARTMENT OF TH GEOLOGICAL	IE INTERI	OR SUBMIT IN TRIPLICA' (Other instructions on verse side)		No. 42-R1424. ND SERIAL NO.	
	IDRY NOTICES AND Form for proposals to drill or to 6 Use "APPLICATION FOR PERMI	REPORTS C		6. IF INDIAN, ALLOTTEE		
1.	Use All Brown Toll 2 Barra		· · · · · · · · · · · · · · · · · · ·	7. UNIT AGREEMENT NAM	ir.	
WELL GAS WELL	X OTHER					
2. NAME OF OPERATOR	8. FARM OR LEASE NAME					
CONSULIDATED (	DUKE 9. WELL NO.	9. WELL NO.				
1860 LINCOLN	1-M					
4. Location of WELL (1 See also space 17 bel At surface		10. FIELD AND POOL, OR WILDCAT				
1640' FSL & 7'	90 FWL			11. SEC., T., R., M., OR BL	11. SEC., T., E., M., OR BLK. AND	
SEC 13 T31N R				SURVEY OR AREA		
				M SEC 13 T31		
14. PERMIT NO.		Show whether DF, 822 KB	RT, GR, etc.)	12. COUNTY OR PARISH SAN JUAN	N.M.	
16.	Check Appropriate Box	To Indicate N	ature of Notice, Report, o	or Other Data	7	
	NOTICE OF INTENTION TO:			SEQUENT REPORT OF:		
TEST WATER SHUT-C	PCLL OR ALTER CAS	ING	WATER SHUT-OFF	REPAIRING WI	ELL	
FRACTURE TREAT	MULTIPLE COMPLET		FRACTURE TREATMENT	XX ALTERING CAS	BING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT	r•	
REPAIR WELL	CHANGE PLANS		(Other)	sults of multiple completios or	n Well	
(Other)			Completion or Rec	ompletion Report and Log forn	n.)	
17. DESCRIBE PROPOSED Of proposed work. I nent to this work.)	R COMPLETED OPERATIONS (Clearly 8 f well is directionally drilled, give	subsurface locat	t details, and give pertinent da ions and measured and true ve C DK IN 2 STAGES	ates, including estimated date ertical depths for all markers	of starting any and zones perti-	
1ST STAGE						
	f DK 6795-97-6808-18-			74-82-86-90. 1 S.P	P.F.	
(o.41 hole 17	holes) acidized w/10	00 gal 15	NE acid.	500 # 20//0	<b></b>	
	c lst stage DK 100,00 avg. 1600# 45 BPM	o gar cro	ssiinked gei & 132	,300 # 20740 Sand.	IIIax	
press. 2500m	avg. 1000# 45 Bill					
	f upper DK 6658-61-64				68-72.	
1 S.P.F. (0.4	l hole 19 holes) acid	ized w/10	00 gal 15% NE acid	00/10		
12-18-80: Frag 3450 avg 2700	c 2Nd stage105,000 ga # 30 BPM.	l crossli	nked gel 232,500# :	20/40 sand. max pr	ess.	
				THE STATE OF THE S		
				CLINED!	. •	
				VALITIATE !		
				MLB 2.1080	1	
•				MAR 26 1300M. OIL CON. COM. DIST. 3		
				I WELL COM.	1	
			·	OIL DIST. 3	<b>7</b>	
18. I hereby certify tha	t the foregoing is true and correct				<del>-</del>	
SIGNED			PKOD. SUPT.	DATE3+2	26-80	
	larel or State office use)					
(This space for Red	eral or State office use)				•	
APPROVED BY	PPROVAL, IF ANY:	TITLE		DATE	<del></del>	

	• . •

## Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Rederal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, or all lands in such State, pursuant to applicable state law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

State or Federal office for specific instructions. Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local

conditioned for final inspection looking to approval of the abandonment. Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local. Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole ; method of closing top of well; and date well site

U.S. GOVERNMENT PRINTING OFFICE: 1969--0-685229

\$87-051

MESA VERDE TOP

36841

66431

DAKOTA TOP



	• • • •