	UNITED STATES RTMENT OF THE INTERIOR OF LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
Do not use this form for prop	DTICES AND REPORTS ON WELLS posals to drill or to deepen or reentry to a different reservoir. CATION FOR PERMIT - " for such proposals	5. Lease Designation and Serial No. SF-078051 6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gae Other Well Well Other		8. Well Name and No.
2. Name of Operator	Attention:	Neal #2
Amoco Production Company	Gail M. Jefferson, Rm 12950	B. API Well No.
3. Address and Telephone No.		3004523950
P.O. Box 800, Denver, Colorad	lo 80201 (303) 830-6157	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or	r Survey Description	Basin Dakota/Mesaverde
······································		11. County or Parish, State
830'FSL 1085FWI	L Sec. 4 T 31N R 11W Unit M	San Juan New Mexico
· · · · · · · · · · · · · · · · · · ·	IATE BOX(s) TO INDICATE NATURE OF NOTICE	
TYPE OF SUBMISSION	TYPE OF ACTI	ON
Notice of Intent	Abandonment Recompletion Plugging Back Casing Repair	Change of Plane New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Altering Casing Other Well Repair	Conversion to Injection
	(Note	 End of the second s second second sec
	has repaired the above referenced well per the attached. estions please contact Khanh Vu at (303) 830-4920 or my	
	DECEN Jun - 5 1 ODL CON. DBST. 3	VED 1995 DITVZ
14. I hereby certify the the foregoing is true and Signed		Staff Asst. 05-30-1995
Approved by Conditions of approval, if any:	Title	JUN 0 1 1995
Title 18 U.S.C. Section 1001, makes it a crime for representations as to any matter within its jurisdic	er any person knowingly and willfully to make to any department or agency of the United ction.	d States any false, ficticious, or fraudulent at a BEREICE
		BY In

Neal 2 - Well Repair - Subsequent

MIRUSU 3/24/95. TOH w/2 3/8" tbg.

Ran CCL and GR to correlate fill and plug back total depth from 6900'-7582' to drill out Lower Dakota.

TIH with tbg and set RBP @ 5550' in order to run CBL and TMD log. Pressure tested casing to 1000#. Held ok.

Ran Thermal Multigate Decay Log and CBL, CCL and GR from 3330-5515'. Est top on 4.5" casing @ 3900'.

TIH w/tbg and removed RBP @ 5550'. TIH w/bit and tbg and drilled out float collar junk and cmt to 7590'.

Perforated from 7572-7584' w/2 jspf, .340 inch diameter, a total of 24 shots fired.

TIH w/3.875" tapered mill to clean out tight spots @ 7337' and 7313-16'. Unable to make any hole @ 7315'. Spent 2 hrs in one spot. Other tight spot @ 7442'. Unable to get PKR in hole to 7555'.

Landed tbg and rigged up to swab to IFL @ 6000¹. Made 9 runs, rec. 12 bbls wtr. Well started to flow. Flowed well for 2 hrs on 2 inch open choke.

TIH and land production string @ 7545'. SICP 400#, SITP 250#.

RDMOSU 4/4/95.