

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Southland Royalty Company		8. Farm or Lease Name Patterson "A" Com
3. Address of Operator P.O. Drawer 570, Farmington, New Mexico 87401		9. Well No. 1-E
4. Location of Well UNIT LETTER <u>G</u> , <u>1640</u> FEET FROM THE <u>north</u> LINE AND <u>1770</u> FEET FROM THE <u>east</u> LINE, SECTION <u>2</u> TOWNSHIP <u>31N</u> RANGE <u>12W</u> NMPM.		10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 6269' GR		12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Perforation & Stimulation
		Production Tubing Report <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/29/80 Perforated the Dakota at 7281', 7288', 7295', 7362', 7368', 7374', 7380', 7390', 7397', 7404', 7411', 7449', 7455', 7506'. Total of 14 holes
Frac'd the Dakota with Total of 167,988 gals 30# gel and 73,155# of 20/40 sand.
AIR 19 BPM, ATP 3300 psi, ISIP none sanded off.

8/30/80 Landed 240 joints (7468') of 2-3/8", 4.70#, J-55, EUE tubing set at 7479'.
SIFT...



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>District Production Manger</u>	DATE <u>September 1, 1980</u>
APPROVED BY <u>Original Signed by FRANK T. CHAVEZ</u>	TITLE <u>SUPERVISOR DISTRICT # 3</u>	DATE <u>SEP 4 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		