

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 14 20 403 2035
2. NAME OF OPERATOR Solar Petroleum, Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribal
3. ADDRESS OF OPERATOR 1099 18th street suite 2900 Denver, Co. 80202-1999	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1230 FSL 2425 FWL	8. FARM OR LEASE NAME Navajo Tribe of Indians G
14. PERMIT NO.	9. WELL NO. 225
15. ELEVATIONS (Show whether DF, etc.) 5285 GL	10. FIELD AND POOL, OR WILDCAT MANY ROCKS - GALLUP
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 1 T31N R17W
	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

RECEIVED

AUG 08 1984

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) TA procedure

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Surf csg 8 5/8" @ 90'

Prod csg 4 1/2" @ 1265

Tbg 2 3/8" @ 1213'

Perfs 1204-1212

TD 1270'

Procedure:

MI service rig

Pull tbg, rods & pump

RIH w/ tbg, displace 25 sx cement 10' above perfs

Pull tbg to top of cement

Displace hole w/ 9.2# mud to surface

Pull tbg to 100+. Keep hole full w/ mud

Displace 25 sx cement to surface

Pull tbg LD tbg

Clean up location, move to next location

RECEIVED
AUG 16 1984
OIL CON. DIV.
DIST. 3

This Approval Or Temporary
Abandonment Expires 8-14-85

18. I hereby certify that the foregoing is true and correct

SIGNED Marie O'Keefe

TITLE Engineering Technician

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE AUG 14 1984

NMOCC

*See Instructions on Reverse Side

APPROVED
AS AMENDED

JOHN S. McKEE
M. MILLENBACH
AREA MANAGER