

F

30-045-27035

8/26/88

F. Loc. 1450S; 1730W Elev. 6149 GL Spd. Comp. TD PB
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ T Gas
 Csg. Perf. Prod. Stim.

BO/D Grav. 1st Del. Gas
 MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oi

TOPS	NITD X	Well Log	TEST DATA						Ref. No.
Ojo Alamo	C-103	Plot X	Schd.	PC	Q	PW	PD	D	
Kirtland	C-104	Electric Log							
Fruitland		C-122							
Pictured Cliffs	Ditr	Dfa							
Chacra	Datr	Dac							
Cliff House									
Menefee									
Point Lookout									
Mancos									
Gallup									
Greenhorn									
Dakota									
Entrada									
	Acres 5/316.06 158.52								

R-8768
 Basin Fr. Coal Co. SJ S 9 T 31N R 10W UK Oper. MERIDIAN OIL INC. Lse. LUCERNE A No. 102

LUCERNE A #102

K-9-31N-10W

MERIDIAN OIL INC.

SF-079634 (WC) et al.
3162.3-1(F) (019)

MAR. 1 9 1990

RECEIVED
MAR 20 1990
OIL CON. DIV.]
DIST. 3

Meridian Oil Incorporated
Southland Royalty Company
P. O. Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells.

Southland Royalty Company

1✓ No. T501 McClanahan, 1450' FSL & 1190' FWL, sec. 13 T. 28 N., R. 10 W.,
San Juan County, New Mexico, lease SF-079634.

Meridian Oil Incorporated

1✓ No. 506 Murphy Com, 1850' FSL & 1180' FWL, sec. 24, T. 30 N., R. 11 W., San
Juan County, New Mexico, lease SF-080113.

2✓ No. 50⁴ Morris A Com, 1150' FNL & 1155' FEL, sec. 15, T. 30 N., R. 11 W.,
San Juan County, New Mexico, lease SF-078138.

3✓ No. 101 Lucerne A Com, 1660' FNL & 1180' FEL, sec. 9, T. 31 N., R. 10 W.,
San Juan County, New Mexico, lease SF-078389.

1✓ No. 102 Lucerne A, 1450' FSL & 1730' FWL, sec. 9, T. 31 N., R. 10 W., San
Juan County, New Mexico, lease SF-078389.

5✓ No. 700 Lloyd C, 790' FNL & 790' FEL, sec. 11, T. 29 N., R. 11 W., San
Juan County, New Mexico, lease NM-03877.

6✓ No. 800 Lloyd A, 1770' FNL & 1850' FEL, sec. 9, T. 29 N., R. 11 W., San
Juan County, New Mexico, lease NM-03486-A.

The subject APDs are rescinded and returned pursuant to your written instructions dated November 29, 1989.

ABANDONED LOCATION

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in an assessment of liquidated damages.

Sincerely,

Ken Townsend

John L. Keller
FOR Chief, Branch of Minerals

7 Enclosures

cc:

NMOCD, Aztec