Form 3160-5 (June 1990)

UNITED STATES

F	ORM	APPR	OVE	D	
Budget	Bure	au No	. 100	04-01	35

(54.1.5 7.555)	DEPARTMENT OF TH	IE INTERIO	OR /	B	adget Bure	au No. 1004-0135		
	A ANDRONE MA	Expires: March 31, 1993						
SUND	5. Lease	5. Lease Designation and Serial No.						
SUNDRY NOTICES AND REPORT ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" - for such popular C					NM-010989			
Use "A	PPLICATION FOR PERMIT" - for s	such Diple	BEIVE		an, Allott ee or Tri			
070 FARMINGTON	(d)	na oci	2 3 1996	7. If Unit	or CA, Agreeme	nt Designation		
1. Type of Well Gas		மா ச	0N. DI	7V7 8. Well I	Name and No.			
Well 2. Name of Operator	Other Attention:			i icius				
·				9. API W	ell No.			
Amoco Production Company 3. Address and Telephone No.	R	atty Haefele			27742			
·				10. Field	and Pool, or Exp	loratory Area		
P.O. Box 800, Denver, Color 4. Location of Well (Footage, Sec., T., R., M.	ado 80201 (3	803) 830-498	8		Fruitland Co			
	• • •			i	nty or Parish, Stat	0		
790' FNL & 790' FEL	Section 25		R11W Uni	į Ca	n Juan, Nev	v Mexico		
12. CHECK APPROI	PRIATE BOX(S) TO INDICAT			PORT, OR OT	HER DATA			
TYPE OF SUBMISSION		TYPE	OF ACTION					
<u></u>	☐ Abandon	ıment		hange of Plans				
Notice of Intent	Recomp			lew Construction	n			
Y Subsequent Report	☐ Plugging ☐ Casing F			ion-Routine Frac Vater Shut-off	turing			
☐ Altering Casing		Casing	Conversion to Injection					
Final Abandonment Notice	Ø Other Re	ecavitation		ispose Water	a completion or	Well Completion or		
			Recompletion R	eport and Log F	orm)	•		
 Describe Proposed or Completed work. If well is directionally drilled 	Operations (Clearly state all perting I, give subsurface locations and m	nent details, and leasured and tru	l give pertinent da e vertical depths i	ites, including of	estimated date	of starting any proposed		
MIRU 9/11/96. NU BOP. Tag fill at 2783' - 60' bridge, tag at 2878' - 10' bridge, tag at 2900' - 10' bridge. Clean out to bottom, circulate well clean. Tag fill at 2780', 2791' and 2810', clean out from 2783-2810'. Clean out from 2778-2986'. Tag at 2751', clean out to 2873'. Circulate with 1500 cfm air and clean out from 2783-2798'. Circulate from 2763-2900' with air, clean out to bottom at 2986'. Flow tested. Tag at 2795', clean out to 2814', circulate with 1500 cfm air. Clean out from 2790-2910', circulate with 1500 cfm air. Clean out from 2814-2986', circulate with 1500 cfm air. Began cavitation. Tag at 2750', clean out from 2750-2814', circulate with 1500 cfm air. Clean out to bottom and circulated w/ air. Flow tested. Cavitated well. Tag at 2798', clean out from 2798-2814', circulated w/ air. Clean out from 2814-2986', circulated with air. Flow tested. Cavitate well. Tag at 2775', clean out from 2775-2986', circulated with air. Flow tested. Tag at 2770', clean out from 2770-2986', circulated with air. Tag at 2751', clean out, circulate with air. Clean out from 2783-2986', circulated with air. Tag at 2820', clean out from 2820-2986', bridges at 2820', 2860', 2870', 2980' and 3' of fill. Tag at 2778', clean out from 2778', circulated with 1500 cfm air. Clean out from 27846-2986', circulated with air. Flow tested. Tag at 2760', clean out from 2760-2846', circulated with 1500 cfm air. Clean out from 27846-2986', circulated with air. Land 2.875" tubing at 2731'. ND BOP. NU WH. RREL 9/30/96.								
4. I hereby certify that the foregoing is true a Signed	nd correct Defele	Title _	Staff Assista	nt	Date10/1	0/96		
This space for Federal or State office use)								
Approved by		Title _		ACCE	Date	LOOND		
itle 18 U.S.C. Section 1001, makes it a crime r representations as to any matter within its j	for any person knowingly and willfully	to make to any dep	partment or agency o	of the United State	s any false, fictiti	ous, or fraudulent statement		
					4111	ם בצו		