

F

30-045-28084

08-03-90

F. Loc. 2030/S: 970/W Elev. 5912 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD. \_\_\_\_\_ PB. \_\_\_\_\_  
 Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. T. \_\_\_\_\_ @ \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stim. \_\_\_\_\_

80/D \_\_\_\_\_ Grav. \_\_\_\_\_ 1st Del. Gas \_\_\_\_\_  
 I.P. \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil \_\_\_\_\_

TOPS		NITD	X	Well Log	TEST DATA						
Ojo Alamo		C-103		Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-104		Electric Log							
Fruitland				C-122							
Pictured Cliffs		Ditr		Dfo							
Chacra		Dotr		Dac							
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
		Acres W/320									

P  
o  
o

BasinFrCoal Co. SJ S 28 T 31N R 11W U L Oper. Amoco Production Co. Lse. Heaton A No. 12

Heaton A #12

L-28-31N-11W

AMOCO PRODUCTION CO.



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
Farmington Resource Area  
1235 Laplata Highway  
Farmington, New Mexico 87401

TAKE  
PRIDE IN  
AMERICA

IN REPLY REFER TO  
SF-078097 et al. (WC)  
3162.3-1.0 (019)

FEB 18 1992

Amoco Production Company  
PO Box 800  
Denver, CO 80201

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos.:

1. No. 12 Heaton "A", Sec. 28, T. 31 N., R. 11 W., San Juan County, New Mexico, lease SF-078097.
2. No. 4 Florance "AB", Sec. 12, T. 29 N., R. 8 W., San Juan County, New Mexico, lease SF-078596-A.
3. No. 1 Florance Gas Com F, Sec. 29, T. 30 N., R. 8 W., San Juan County, New Mexico, lease SF-080597.

The subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller  
Chief, Branch of Mineral Resources

3 Enclosures

CC:  
New Mexico Oil Conservation Division, Aztec, NM 87410

RECEIVED  
FEB 19 1992  
OIL CON. DIV.  
DIST. 3

ABANDONED LOCATIONS