

UNITED STATES
DEPARTMENT OF INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICE AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

5. Lease Designation and Serial No.
SF-078772

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

1. Type of Well
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
WILLIAMS PRODUCTION COMPANY

3. Address and Telephone No.
PO BOX 3102 MS 37-2, TULSA, OK 74101 (918) 573-6254

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1964' FNL & 1960' FEL, SW/4 NE/4, SEC 33-T32N-R06W

7. If Unit or CA, Agreement Designation
ROSA UNIT

8. Well Name and No.
ROSA UNIT #355

9. API Well No.
30-045-30192

10. Field and Pool, or Exploratory Area
BASIN FRUITLAND COAL

11. County or Parish, State
SAN JUAN, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

Notice of Intent
☒ Subsequent Report
Final Abandonment

TYPE OF ACTION

Abandonment
Recompletion
Plugging Back
Casing Repair
Altering Casing
Other Replace tbg

Change of Plans
New Construction
Non-Routine Fracturing
Water Shut-Off
Conversion to Injection
Dispose Water
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-07-2001 Road rig & equipment to location. Spotted rig & equipment. Too windy to set-up mast. Made well secure until morning

12-08-2001 RU rig & equipment. Well head blocked with ice. Broke ice plug & cleared wellhead. Pumped 5 bbls water down tbg & dropped standing valve. Pumped 12 bbls water down tbg. Pressure tested tbg with rig pump. Pumped into tbg @ 1 BPM. ND X-mas tree & NU with BOP. TOO H w/ 32 jts tbg, pressure testing with rig pump. Located 4 jts with pin holes. TIH w/ tbg. Attempted to pressure test, pumped into tbg @ 1 BPM. Fished standing valve with sand line. Ordered out tbg float. Spotted float & made well safe for night

12-09-2001 Singled down w/ 2-7/8" prod tbg. Singled & measured in hole with new 2-7/8" prod tbg. Landed tbg @ 3105.13', leaving 14' rat hole. Tbg landed as follow: 1/2" mule shoe on bottom, F-nipple one jt up, 98 jts of 2-7/8" new J-55, 8rd, 6.5# tbg. ND w/ BOP, NU X-mas tree. Rigged well for production. LD rig mast & moved rig clear of well making room for swabbing unit. Unable to get trucks to move rig until morning.

12-10-2001 Loaded out with rig & equipment. Road rig & equipment to Farmington yard

14. I hereby certify that the foregoing is true and correct

Signed Tracy Ross
TRACY ROSS

Title Production Analyst Date December 11, 2001


(This space for Federal or State office use)

Approved by _____

Title _____

Date DEC 21 2001

Conditions of approval, if any:



Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD

K