

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
James P. Woosley

3. ADDRESS OF OPERATOR
Box 1227, Cortez, CO 81321

4. LOCATION OF WELL (Report location clearly and in accordance with State requirements. See also space 17 below.)
At surface
2030' FNL. & 750' FEL

5. LEASE DESIGNATION AND SERIAL NO.
14-20-603-585

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Navajo AA

9. WELL NO.
25

10. FIELD AND POOL, OR WILDCAT
North Many Rocks Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 18, T32N R17W
SE 1/4 NE 1/4

12. COUNTY OR PARISH
San Juan

13. STATE
NM

14. PERMIT NO.
Apr. 20, 1977

15. ELEVATIONS (Show whether OP, RT, OR, Etc.)
5382 GL

RECEIVED
DEC 27 1982
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged & abandoned hole as follows:

1. set cement plug from T.D. 1480' back to 1355' with 26 sks.
2. staged mud from 1355' back to 90'
3. set cement plug from 90' back to surface with 16 sks.
4. no abandonment marker because it is in the middle of a wash.

RECEIVED
JUN 15 1983
OIL CON. DIV
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED James P. Woosley TITLE operator DATE 12/15/82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

2 Instructions on Reverse Side

APPROVED
AS AMENDED

FEB 06 1985
John M. Millenbach
M. MILLENBACH
AREA MANAGER

NMCCC