| Form | 9-331 |
|------|-------|
| (May | 1963) |

| Form 9-331 (May 1963) | | UNITED STATES MENT OF THE INTER GEOLOGICAL SURVEY | SUBMIT IN TRIPLICATE (Other instructions on reverse side) | | eau No. 42-R1424 N AND SERIAL NO. |
|--|--|---|---|---|--------------------------------------|
| | SUNDRY NO this form for proper Use "APPLIC | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | | | |
| OIL XX GA | AS OTHER | 7. UNIT AGREEMENT NAME | | | |
| 2. NAME OF OPERAT | гоr | 8. FARM OR LEASE NAME | | | |
| James P. Wo | oosley | Navajo AA 9. well no. 26 | | | |
| 3. ADDRESS OF OPE | RATOR | | | | |
| Box 1227, 0 | Cortez, CO 81 | | | | |
| LOCATION OF WELL (Report location clearly and in accordance with any state send rements.) At surface 700' FNL 2480' FEL 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etter) | | | | North Many Rocks Gallu 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 1. W 4 NE4 Sec 18 | |
| | | | | | |
| 14. PERMIT NO. | | 15. ELEVATIONS (Show whether | DP, RT, GR, etc. P. P. C. V. | 12. COUNTY OR PARIS | H 13. STATE |
| 5-28-77 | | 5323 GL | | San Juan | NM |
| 16. | Check A | ppropriate Box To Indicate | Nature of Notice, Report, or | Other Data | |
| | NOTICE OF INTE | NTION TO: | SUBSEC | QUENT REPORT OF: | |
| TEST WATER SI | HUT-OFF | PULL OR ALTER CASING | WATER SHUT-OFF | REPAIRING | WELL |
| FRACTURE TREA | T | MULTIPLE COMPLETE | FRACTURE TREATMENT | ALTERING | CASING |
| SHOOT OR ACID | IZE | ABANDON* | SHOOTING OR ACIDIZING | ABANDONM | ENT. |

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

(Other) ...

Plugged as follows:


REPAIR WELL

(Other)

- set cement plug from T.D. 1496' back to 1375' with 25 sks.
- staged mud from 1375' back to 85'
- set cement plug from 85' to surface with 15 sks. 3.
- set plug & abandon marker with 1 sks.

CHANGE PLANS

will reseed area between July & Sept. 15, 1923.



| 18. I hereby certify that the foregoing is true and co | orrect | | |
|--|--------|----------|---|
| SIGNED COMPANY HOUSE | / | operator | $\triangle \mathbf{p} \mathbf{p} \mathbf{p}^{2} \hat{\mathbf{p}}^{5} \hat{\mathbf{p}}^{2} = \mathbf{p}$ |
| (This space for Federal or State office use) | | | |
| APPROVED BYCONDITIONS OF APPROVAL, IF ANY: | TITLE | | DATE 11 4 - 1384 (SQTA MAN) - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - |

*See Instructions on Reverse Side

M. MILLENBACH AREA MANAGER

