

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name Unknown
2. Name of Operator James Hatcher	8. Farm or Lease Name Marjory M. Greer
3. Address of Operator Bloomfield Oilfield Service Co. Box 1641 Bloomfield, N.M.	9. Well No. Red Mountain # 10
4. Location of well UNIT LETTER B 75 FEET FROM THE N LINE AND 1710 FEET FROM THE E LINE, SECTION 29 TOWNSHIP 20N RANGE 9W NMPM.	10. Field and Pool, or Wildcat Menefee
15. Elevation (Show whether DF, RT, GR, etc.)	12. County McKinnley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-28-81 - Moved Rig and equipment on location and rigged up.

9-29-81 - Picked up 3 7/8 bit and tubing, cleaned out hole to 445 mixed and pumped 15 sacks class A cement. Plug set from 445 to 320. Pulled tubing back to 150, mixed and pumped 15 sacks class A cement. Plug set from 150 to 30. Pulled to 30 mixed and pumped 10 sacks class A cement. Plug set from 30 to surface.

9-30-81 - Rig down and move off location.

10-9-81 - Clean location level pits and install dry hole marker.

10-9-81 - Location ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James Hatcher TITLE _____ DATE 10-12-81

APPROVED BY Jeff A. Edmister TITLE Deputy Oil & Gas Inspector DATE 10-15-81